
**Pacific Northwest
National Laboratory**

Operated by Battelle for the
U.S. Department of Energy

Fluor Hanford, Inc. Groundwater and Technical Integration Support (Master Project) Quality Assurance Management Plan

N.J. Fix

February 2008

Prepared for the U.S. Department of Energy
under Contract DE-AC05-76RL01830



DISCLAIMER

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency thereof, nor Battelle Memorial Institute, nor any of their employees, makes **any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights.** Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof, or Battelle Memorial Institute. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or any agency thereof.

PACIFIC NORTHWEST NATIONAL LABORATORY

operated by

BATTELLE

for the

UNITED STATES DEPARTMENT OF ENERGY

under Contract DE-AC05-76RL01830

Printed in the United States of America

Available to DOE and DOE contractors from the
Office of Scientific and Technical Information,

P.O. Box 62, Oak Ridge, TN 37831-0062;

ph: (865) 576-8401

fax: (865) 576-5728

email: reports@adonis.osti.gov

Available to the public from the National Technical Information Service,
U.S. Department of Commerce, 5285 Port Royal Rd., Springfield, VA 22161

ph: (800) 553-6847

fax: (703) 605-6900

email: orders@ntis.fedworld.gov

online ordering: <http://www.ntis.gov/ordering.htm>



This document was printed on recycled paper.

**The Fluor Hanford, Inc. Groundwater and
Technical Integration Support (Master Project)
Quality Assurance Management Plan**

N.J. Fix

February 2008

Prepared for
the U.S. Department of Energy
under Contract DE-AC05-76RL01830

Pacific Northwest National Laboratory
Richland, Washington 99352

Revision 2

**Fluor Hanford, Inc. Groundwater and Technical Integration
Support (Master Project)
Quality Assurance Management Plan**


Project # 52347

Prepared by
Pacific Northwest National Laboratory
Richland, Washington 99352


Issue Date: January 2008

Approval:

D.D. Dauble, Product Line Manager
Environmental Science & Technology

 1-8-08
Date

M.D. Freshley, Project Manager
Fluor Hanford, Inc.
Groundwater and Technical Integration (Master Project)

 1/8/07
Date

Concurrence:

N.J. Fix, Project Quality Engineer
Quality Assurance Services

 01/08/2008
Date

Quality Assurance Management Plan Revision History				
Formal revisions to this Quality Assurance Management Plan (QAMP) are listed below.				
Rev. #	Comments	Rev. Date	Effective Date	Approvals
0	Initial QAMP release.	N/A	1/9/07	
1	Updated Section 17 software. Removed references to PNNL-15014 and inserted relevant text from that quality assurance project plan. Updated project lists. General editorial/consistency corrections.	10/30/07	11/1/07	
2	Update Section 14.0 to add electronic records management, minor editorial corrections made.	12/1/07	12/07	

Summary

The scope of the Fluor Hanford, Inc. Groundwater and Technical Integration Support (Master Project) is for Pacific Northwest National Laboratory staff to provide technical and integration support to Fluor Hanford. This work includes conducting investigations at the 300-FF-5 Operable Unit and other groundwater operable units, and providing strategic integration, technical integration and assessments, remediation decision support, and science and technology. The primary projects under this Master Project include the following:

- 300-FF-5 Phase III Feasibility Study Project
- Support Integration and 200 Area Groundwater Operable Units Project
- Technology Management and Integration Support Project
- Remediation Decision Support Project
- Remediation and Closure Science Project.

Other projects will be defined and included within the Master Project throughout the fiscal year, and will be incorporated into the Master Project Plan.

This Quality Assurance Management Plan provides the quality assurance requirements and processes that will be followed by the Fluor Hanford, Inc. Groundwater and Technical Integration Support (Master Project) and all releases associated with the Fluor Hanford, Inc. Groundwater Remediation Project. This plan is based on the requirements in the *EPA Requirements for Quality Assurance Project Plans (QA/R-5)* (EPA/240/B-01/003¹) in accordance with the *Hanford Federal Facility Agreement and Consent Order* (commonly referred to as the Tri-Party Agreement [Ecology et al. 1989²]); DOE Order O 414.1C, *Quality Assurance*³; and 10 *Code of Federal Regulations* 830, Subpart A, “Quality Assurance Requirements.”⁴ The *Price-Anderson Amendments Act*⁵ also applies to this project.

¹EPA/240/B-01/003 (QA/R-5). 2001. *EPA Requirements for Quality Assurance Project Plans (QA/R-5)*. U.S. Environmental Protection Agency, Washington, D.C.

²Ecology – Washington State Department of Ecology, U.S. Environmental Protection Agency, and U.S. Department of Energy. 1989, as amended. *Hanford Federal Facility Agreement and Consent Order*. Document No. 89-10, Olympia, Washington.

³DOE O 414.1C. 2005. *Quality Assurance*. U.S. Department of Energy, Washington, D.C.

⁴10 CFR 830, Subpart A, “Quality Assurance Requirements.” *U.S. Code of Federal Regulations*.

⁵Price-Anderson Amendments Act. *Energy Policy Act of 2005*. Title VI—Nuclear Matters, Subtitle A—Price-Anderson Act Amendments, Section 601 et. seq. Public Law 109-58, as amended. 42 USC 15801 et seq.

Additionally, project management has determined that the *Hanford Analytical Services Quality Assurance Requirements Documents* (HASQARD [DOE/RL-96-68⁶]) apply to the Groundwater Monitoring and Reporting Project and analytical work on other projects. The Pacific Northwest National Laboratory document for implementing HASQARD requirements is *Conducting Analytical Work in Support of Regulatory Programs*.⁷

⁶DOE/RL-96-68. 1998. *Hanford Analytical Services Quality Assurance Requirements Documents*. HASQARD, Volumes 1, 2, 3, and 4. U.S. Department of Energy, Richland Operations Office, Richland, Washington.

⁷CAWSRP – *Conducting Analytical Work in Support of Regulatory Programs*. 2006. Pacific Northwest National Laboratory, Richland, Washington. Available online at <http://etd.pnl.gov/docs/conducting-work/index.stm>

Abbreviations and Acronyms

AEA	<i>Atomic Energy Act</i>
ASCII	American Standard Code for Information Interchange
ASTM	American Society for Testing and Materials
ATS	Assessment Tracking System
CAWSRP	<i>Conducting Analytical Work in Support of Regulatory Programs</i>
CD	compact disk
CERCLA	<i>Comprehensive Environmental Response, Compensation, and Liability Act</i>
CFR	<i>Code of Federal Regulations</i>
CMP	Configuration Management Plan
DOE	U.S. Department of Energy
DQO	data quality objectives
DVD	digital versatile disc
EPA	U.S. Environmental Protection Agency
ERICA	Electronic Records and Information Capture Architecture
ESL QAP	<i>Environmental Sciences Laboratory Quality Assurance Plan</i>
FH	Fluor Hanford, Inc.
FY	fiscal year
GS	General Services
HASQARD	<i>Hanford Analytical Services Quality Assurance Requirements Documents</i>
ICN	Interim Chance Notice
IRI	Information Resource Inventory
LOI	letter of instruction
LRB	laboratory record book
M&TE	measuring and test equipment
MDA	minimum detectable activity
MDL	method detection limits
MOA	Memorandum of Agreement
NQA	Nuclear Quality Assurance
OJT	on-the-job-training

PAAA	<i>Price-Anderson Amendments Act</i>
PNNL	Pacific Northwest National Laboratory
PMP	project management plan
QA	quality assurance
QAMP	Quality Assurance Management Plan
QAPjP	Quality Assurance Project Plan
QC	quality control
RCRA	<i>Resource Conservation and Recovery Act of 1976</i>
RDR	Review Document Record
RDS	Remediation Decision Support
RIDS	Records Inventory and Disposition Schedule
RPG	requirements, procedures and guidelines
RTDI	Records Transfer/ Data Input Form
SAP	Sampling and Analysis Plan
SBMS	Standards-Based Management System
SC	Safety Class
SDD	Software Design Description
SOW	statements of work
SRS	Software Requirements Specification
SS	Safety Significant
TRIM	Total Records Information Management
VOC	volatile organic constituent
VVP	Verification and Validation Plan
VVR	Verification and Validation Review
WAC	<i>Washington Administrative Code</i>
WBR	workstation backup and restore
WBS	Work Breakdown Structure
WPA	Work Package Authorization

Contents

Summary	iii
Abbreviations and Acronyms	v
1.0 Quality Assurance Plan Distribution	1
2.0 Introduction	1
2.1 Title	1
2.2 Client	1
2.3 Authorizing Document	1
2.4 Quality Assurance Requirements	1
2.5 Special Requirements or Specifications	3
2.6 Project Scope	3
2.7 Change Control (Scope, Schedule, Budget)	4
3.0 Project Organization and Responsibilities.....	5
3.1 Responsibilities of Key Personnel.....	5
3.2 Other Work Services	7
3.2.1 Analytical Services.....	7
3.2.2 Sampling.....	8
3.2.3 Well Drilling, Sampling, and Construction Services	8
3.2.4 Geophysics	8
3.2.5 Field Measurements	8
3.2.6 Other Services	8
3.3 Work Conducted by Project Staff.....	8
3.4 Field Work.....	9
4.0 Data Quality Objectives	9
5.0 Test Plans and Procedures	10
5.1 Test Planning and Performance.....	10
5.1.1 Developing the Test Plan	10
5.1.2 Test Performance.....	11
5.2 Procedures	11
5.2.1 Project Procedures	12
5.2.2 Water-Level Procedures	12
5.2.3 Analytical Procedures.....	12
5.2.4 Calibration Procedures	13
5.2.5 Common Data Quality Calculations.....	14

5.2.6	Well Drilling and Construction Procedures	14
5.2.7	Water and Sediment Sample Collection Procedures	15
5.2.8	Receiving and Handling Samples.....	15
5.2.9	Sediment Physical Analysis Procedures.....	15
6.0	Data Generation and Acquisition	16
6.1	Experimental Design (Sampling Process Design).....	16
6.2	Sampling Methods.....	16
6.3	Sample Handling and Custody	16
6.4	Analytical Methods	16
7.0	Data Reduction, Verification, and Reporting	17
7.1	Data Reduction.....	17
7.2	Sample Data Tracking and Verification	17
7.3	Sample Data and Tracking for Soil and Sediment Samples	17
7.4	Data Reporting	18
8.0	Analytical Quality Control Checks.....	18
9.0	Assessments.....	19
9.1	Assessment Planning and Documentation.....	19
9.2	Subcontractor Collaborator Assessments	22
10.0	Preventive Equipment Maintenance	22
11.0	Specific Routine Procedures Used to Assess Data Precision, Accuracy, and Completeness	22
12.0	Corrective Action	22
12.1	Project Corrective Actions Resulting from Assessments	22
12.2	Unplanned Deviations	23
12.3	Planned Deviations.....	23
12.4	Measuring and Test Equipment Calibration Discrepancies	23
13.0	Quality Assurance Reports to Management	24
14.0	Records	24
14.1	Records Control.....	24
14.2	Records Transfer to Storage	25
14.3	Electronic Data/Records Management	25
14.3.1	Workstations.....	26
14.3.2	Servers.....	26
15.0	Procurement Control	27
15.1	Sample Collection and Handling.....	27
15.2	Groundwater and/or Sediment Analytical Measurements.....	27
15.3	Other Hanford Contractor Services	27
15.4	Technical Services from Subcontractors	28

16.0	Staff Training.....	28
17.0	Software Control	29
17.1	Software and Software Applications	30
17.1.1	Minimum Documentation Requirements	30
17.1.2	Software Requirements Specification	31
17.1.3	Software Design Description.....	31
17.1.4	Verification and Validation Plan	32
17.1.5	Verification and Validation Report	32
17.1.6	User Documentation.....	33
17.1.7	Configuration Management Plan.....	33
17.2	Software Use in Analysis	33
17.3	Utility Calculations.....	34
18.0	Nonconformances and Deficiencies	36
19.0	Document Control	36
19.1	Project Quality Assurance Plan Control.....	36
19.2	Technical Procedure Control.....	36
19.3	Administrative Procedure/Instruction Preparation and Control	39
19.4	Groundwater Monitoring Plans	39
19.4.1	RCRA Interim-Status Plans.....	39
19.4.2	RCRA Final-Status Plans	39
19.4.3	CERCLA Sampling and Analysis Plans.....	40
19.4.4	Other Monitoring Plans	40
19.5	Test Plans and Other Work Documents	40
19.6	Field Notebooks and Laboratory Record Books	41
20.0	References	42
Appendix A	The Fluor Hanford, Inc. Groundwater and Technical Integration Support (Master Project) Quality Control Plan	A.1
Appendix B	Experimental and Modeling Procedures for the Subsurface Science Representative Sites Task	B.1

Figures

Figure 3.1. Project Interfaces	6
Figure 9.1. Self-Assessment Planning Form.....	20
Figure 9.2. Self-Assessment Results.....	21
Figure 19.1. Interim Change Notice.....	37

Tables

17.1 Software Risk Management Examples	35
--	----

1.0 Quality Assurance Plan Distribution

Pacific Northwest National Laboratory (PNNL) document control will distribute this Quality Assurance (QA) Management Plan (QAMP) internally to PNNL, the Fluor Hanford, Inc. Groundwater Remediation Project, and to the U. S. Department of Energy, Richland Operations Office as requested. PNNL distribution will be accomplished through hard copies sent to Project Managers and Task Leads, as well as access to a PNNL SharePoint site for the Master Project. The Project Manager will determine the final PNNL and external distribution list, and who will have access to the SharePoint site. Also, the QA Management Plan will be published in accordance with the Standards-Based Management System (SBMS) subject area, “[Publishing Scientific and Technical Information](#)” (PNNL 2007d).

2.0 Introduction

2.1 Title

The title of this project is as follows: Fluor Hanford, Inc. Groundwater and Technical Integration (Master Project).

2.2 Client

The client is Fluor Hanford, Inc., for the U.S. Department of Energy, Richland Operations Office; both are located in Richland, Washington.

2.3 Authorizing Document

Work is authorized by specified contract releases that are received and revised throughout the fiscal year from Fluor Hanford (FH). The list of projects that are received are summarized in a table that is maintained on the SharePoint site for the Master Project:

<https://pnlweb.pnl.gov/projects/FP/Shared%20Documents/Forms/AllItems.aspx>.

This list will be maintained and periodically updated as additional releases are received. There is a set of projects under the master that include the following: Technology Management and Integration Support; Remedial Decision Support; Remediation and Closure Science; and Integration Support, which supports the integration function of the Groundwater Remediation Project at Fluor Hanford. Other projects support specific technical aspects of the FH work scope.

2.4 Quality Assurance Requirements

The projects contained within the Master Project shall comply with the requirements in the U.S. Environmental Protection Agency (EPA) *Requirements for Quality Assurance Project Plans (QA/R-5)* (EPA/240/B-01/003) in accordance with the *Hanford Federal Facility Agreement and Consent Order*, commonly referred to as the Tri-Party Agreement (Ecology et al. 1989). The Master Project Quality Assurance Program and individual project-specific quality assurance project plans (QAPjPs) are also based on the QA requirements of DOE Order 414.1C, *Quality Assurance*, and 10 *Code of Federal*

Regulations (CFR) 830, Subpart A, *Quality Assurance Requirement*, as delineated in the PNNL SBMS. The projects are subject to the *Price Anderson Amendments Act* (PAAA) as defined in the PNNL PAAA Program and implemented through the SBMS subject area, "[Price-Anderson Amendments Act](#)" (PNNL 2007d). Additionally, the Master Project has determined that the *Hanford Analytical Services Quality Assurance Requirements Documents* (HASQARD; DOE/RL-96-68) apply to analytical work on other projects. The PNNL document for implementing HASQARD requirements is *Conducting Analytical Work in Support of Regulatory Programs* (CAWSRP) located at <http://etd.pnl.gov/docs/conducting-work/index.stm>.

In addition, FH has imposed quality levels upon various projects contained within this Master Project. For clarity and consistency the FH quality levels are defined as follows:

"The environmental graded approach shall be documented in project documents such as Quality Assurance Project Plans (QAPjPs) or Sampling and Analysis Plans (SAPs) as appropriate and as required by the governing standard(s) (e.g., EPA QA/R-5).

- a. Quality level 1 shall be assigned to Safety Class (SC) items and associated services and items and associated services posing a high project risk.
- b. Quality Level 2 shall be assigned to safety significant (SS) items and associated services not designated as Quality Level 1 and items and associated services posing a medium project risk.
- c. Quality Level 3 shall be assigned to:
 1. General Service (GS) items and associated services posing a low project risk, but, based on engineering evaluation, require additional controls beyond standard commercial practices.
 2. Any item or service with the potential to cause radiological harm (in the present or future) which has not been designated as Quality Level 1 or 2.
 3. Items where independent verification is required by a national consensus standard (e.g., AWS D1.1; ANSI B31.3; ASME Section VIII) which have not been designated as Quality Level 1 or 2.

NOTE: *The following are examples of GS items and services which may be graded as Quality level 3, based on an engineering evaluation:*

- *Item or service performs a safety function (defense-in-depth), but does not meet the criteria for SC or SS.*
 - *Item or service performs a function to minimize impact to the environment.*
 - *Item or service performs a function to minimize damage to the facility or its critical equipment.*
- d. Quality Level 0 shall be assigned to GS items and services procurements not designated as Quality Level 1, 2 or 3. The controls inherent in standard commercial practices are acceptable" (HNF-PRO-259, Revision 5).

NQA-1-2000 standards always apply to FH Quality Level 1 and 2 items, but FH can impose NQA-1-2000 standards on Quality Level 3 or 0 products. The additional requirements must be specifically identified in the SOWs and/or contract releases received from FH.

2.5 Special Requirements or Specifications

DOE Orders 435.1, *Radioactive Waste Management*; 5400.5, *Radiation Protection of the Public and Environment*; and 450.1, *Environmental Protection Program*, apply to the Master Project to ensure that activities related to the radioactive materials and samples are protective of human health and the environment and fulfill PNNL environment and stewardship requirements. Compliance and waste-cleanup timetables and implementation milestones are established in the Tri-Party Agreement (Ecology et al. 1989) to achieve compliance with remedial action provisions of the *Comprehensive Environmental Response, Compensation and Liability Act* (CERCLA) and the treatment, storage, and disposal unit regulations and corrective action provisions promulgated under the *Resource Conservation and Recovery Act* (RCRA).

Field experiment and sampling and analysis plans (see Sections 4.0 and 5.0) require development of test plans and will be based on applying the data quality objectives (DQO) process, in accordance with the *Guidance on Systematic Planning Using the Data Quality Objectives Process (QA/G-4)* (EPA/240/B-06/001). Field experiment test plans, procedures, and sampling and analysis plans are reviewed and approved at the project level and updated as necessary.

Computer modeling and database activities for the project shall comply with the software requirements as specified in PNNL's SBMS subject areas, "[Software](#)" (PNNL 2007i) and "[Safety Software](#)" (PNNL 2007g). Specific safety software and software requirements for the activities are described in Section 17.0 and are based on a graded approach.

2.6 Project Scope

The scope of the Fluor Hanford, Inc. Groundwater and Technical Integration Support (Master Project) is to provide groundwater and technical integration support to FH, including CERCLA groundwater operable unit investigations at 300-FF-5 and other CERCLA operable units, strategic integration, technical integration and assessments, remediation decision support, and science and technology. This work scope includes the following primary projects:

- **Groundwater and Technical Integration Support (Master) Project** – Perform project management and oversight of the work scope conducted as part of the Master Project. Review and approve individual contract releases and identify the Project Managers, develop and implement a project management plan, health and safety plan, and QA Management Plan to control the work scope under the Master Project. Perform assessments and work with Project Managers to implement corrective actions.
- **300-FF-5 Phase III Feasibility Study Project** – Field and laboratory work to characterize uranium contamination in the 300 Area, documentation of the baseline risk assessment, groundwater model application to groundwater flow and solute transport in the 300 Area, 300-FF-5 groundwater monitoring, final screening of remedial technologies, and project management.
- **Technology Management and Integration Support to Groundwater and Vadose Zone Project** - provide direct support to the FH Groundwater Remediation Project for project management and reporting, developing and maintaining project baselines, quality assurance, health and safety, and records coordination as well as integration of activities leading to remediation decisions for groundwater, soil, and waste sites, so that it is obvious to the regulators,

stakeholders and the public that activities are well coordinated. The management and integration portion of this project will also serve as the point of contact for additional contract releases by FH for related work scope. The scope of work includes subtasks for maintaining the hardware, software, and other tools needed to assess the impact of Hanford wastes on groundwater, the Columbia River, and users of those resources for the purpose of informing cleanup decisions. As part of this project, existing software packages (System Assessment Capability and the Site-Wide Groundwater Model) will be maintained on cold standby.

- **Remediation Decision Support Project** - The Remediation Decision Support (RDS) Project coordinates an integrated systems approach to provide data and information supporting remediation decisions. The RDS Project facilitates development of consistent data, parameters, and conceptual models to resolve technical issues and support efforts to estimate contaminant migration and impacts.
- **Remediation and Closure Science Project** – Develop scientific data to support development of consistent and defensible conceptual models, develop new methods and models for predicting subsurface contaminant fate and transport in the Hanford subsurface, and developing and enhancing new technologies for remediation of subsurface contamination in the vadose zone and groundwater.

The scope of this Master Project QA Management Plan is to provide PNNL staff with the program-specific planning, execution, assessment of work, and controls necessary to provide products/solutions and services of the highest quality consistent with project risks, PNNL SBMS subject area, “[Policies and Standards](#)” (PNNL 2006b), and the needs, expectations, and resources of the client.

Management processes, including planning, scheduling/execution, and providing resources for work to provide project deliverables based on risk, safety, life cycle, complexity are described in *The Fluor Hanford Groundwater and Technical Integration Support (Master Project) Project Management Plan* (Project No. 52347, current revision).

2.7 Change Control (Scope, Schedule, Budget)

Project scope, schedule, and budget baseline are compiled, tracked, and reported using project control systems in accordance with FH direction. The scope, schedule and budgets for the individual contract releases (projects) are tracked separately and reported to FH.

Changes in work scope, schedule, or budget may be necessary during the year. Changes may be requested of subcontractors by PNNL that will result in a change to the statements of work (SOWs) due to revisions of work scope, schedule, and/or budget. These changes will be documented in revisions or addendums to the existing SOWs, and a PNNL Subcontracts Supplement Form shall be completed.

Administrative changes requested of subcontractors that are approved by the Project Manager may be made by verbal or electronic message authorization. Written documentation of the verbal changes and electronic messages should be maintained in the permanent project files. These changes may only be made if technical work scope and budget are not affected significantly.

3.0 Project Organization and Responsibilities

Line authority, quality assurance authority and support within PNNL, and client interfaces are shown organizationally in Figure 3.1. The responsibilities of key PNNL personnel are summarized in Section 3.1. Changes to organizational/interface structures shown in Figure 1 that do not reflect a change in the overall scope of the activities or a change of requirements will not require a QA Management Plan revision and will be incorporated into the next required revision of the Plan.

3.1 Responsibilities of Key Personnel

- **Master Project Manager** — provides overall direction to Project Managers within PNNL necessary to accomplish project objectives. Responsible for development and implementation of the project management plan, health and safety plan, and QA Management Plan. Serves as the primary client interface for receiving contract releases and assigning Project Managers and assures the QA Management Plan is implemented.
- **Project Managers** — provides overall direction to task managers and project personnel within PNNL necessary to accomplish project objectives; coordinates and executes project controls associated with scope, schedule, and budget baselines; reports on project status; assures that the project is staffed with technically qualified personnel; serves as primary client interface to assure that customer expectations are met in terms of quality, cost, and schedule; and assures the QA Management Plan is implemented.
- **Task Leaders** — oversees task-specific planning, control, communications, and progress reporting; prepares scope, resource needs, cost baseline, and deliverables; assures quality and timeliness of the work, in accordance to plans, policies, and procedures; provides monthly reports; interfaces with DOE, other contractors, subcontractors, and other Task Leaders.
- **Principle Investigators** — provides task-specific technical plans, communications, and progress reporting to the Task Leader; prepares technical details of the task plan; assures technical quality of the work; supports the Task Leader to assure work is performed on schedule, within budget, and in accordance to plans, policies, and procedures; assigns and directs work of project staff; and interfaces with DOE, other contractors, subcontractors, and other investigators.
- **Project Quality Engineer** — provides guidance and direction to Project Manager, Task Leads, and project staff within PNNL on PNNL QA Program requirements; performs assessments to assure quality of the work; develops, updates, and approves the QA Management Plan and lower level QAPjPs; and reviews and approves appropriate work plans and procedures.
- **Other Project Staff** — assures technical quality of the work and that it is performed on schedule, within budget, and in accordance with plans, policies, and procedures; and reports concerns, such as unsafe conditions, and stops work as necessary.




Figure 3.1. Project Interfaces

3.2 Other Work Services

Other work services for various portions of project work will be through the purchasing process. The general scope of work, work requirements, specifications, and quality assurance requirements are communicated via a contracting mechanism to various subcontractors (see Section 15.0). SOWs to subcontractors used for groundwater and sediment sample analysis will require compliance with the HASQARD (DOE/RL-96-68) and/or the *EPA Requirements for Quality Assurance Project Plans (QA/R-5)* (EPA/240/B-01/003); 10 CFR 830, Subpart A, *Quality Assurance Requirements*; DOE Order 414.1C, *Quality Assurance*; and specific requirements to be achieved by appropriate quality documents. The SOW will include instructions for inspecting/accepting supplies and consumables used for this project.

Subcontracts for drilling, sediment sampling, groundwater sampling, and associated support activities will include the following:

- Fluor Hanford performs drilling, sediment and water sample collection related to drilling, and well construction services.
- Other subcontractors may provide civil surveys, special analytical services, or other services.

Project staff will perform sampling and measurements according to written and approved internal procedures. Analytical activities conducted by the project staff shall be conducted in accordance with written standard operating procedures. Field measurements will be conducted in accordance with in-house operating procedures. Project staff members are responsible for preparing data reports that summarize the results of analyses, quality control data for the method used and identification of data qualifiers. The results and raw data will be included in the project records.

3.2.1 Analytical Services

Project participants are responsible for preparing data packages that include the following:

- Sample receipt and tracking documentation, including identification of the organization and individuals performing the analysis; names and signatures of the responsible analysts; sample holding time requirements; references to applicable chain-of-custody procedures; and dates of sample receipt, extraction (if applicable), and analysis.
- Quality control data, as appropriate for the methods used, including (as applicable) matrix spike/matrix spike duplicate data, recovery percentages, precision and accuracy data, laboratory blank data, and identification of any nonconformance that may have affected the laboratory's measurement system during the time period in which the analysis was performed.
- Analytical results or data deliverables, including reduced data and identification of data qualifiers and contractually defined reporting comments.

These requirements as well as quality assurance and technical requirements are specified in the SOW to the other national laboratories and university project participants as necessary.

3.2.2 Sampling

The organization collecting soil or water samples, generally PNNL, is responsible for (1) obtaining the samples; (2) delivering samples to the laboratory; and (3) delivering completed paperwork to implementing sample tracking. All activities associated with the sample collection, sample handling, sample labeling, and custody of the samples in the field shall be consistent with the recommendations and protocols provided in Chapter 4, Section 4.2 through 4.4 in *RCRA Ground Water Monitoring Technical Enforcement Guidance Document* (National Water Well Association 1986), *Test Methods for Evaluating Solid Waste, SW-846* (EPA/SW-846), and the *Handbook for Analytical Quality Control in Water and Wastewater Laboratories* (EPA-600/4-79/019). Activities associated with the sample collection, sample handling, sample labeling, and custody of the samples in the field shall be consistent with the SOW.

3.2.3 Well Drilling, Sampling, and Construction Services

FH provides well-drilling and construction subcontractors and oversight on the Hanford Site. FH is responsible for (1) well drilling design specifications and contract management, (2) site preparation and documentation requirements, (3) sediment and water sample collection during drilling, (4) supporting hydrologic tests conducted during drilling, and (5) well construction, development, and sample pump installation. Well construction will meet the requirements of *Washington Administrative Code* (WAC) 173-160. Well drilling and construction, sediment and water sampling, testing support, and associated quality requirements will be specified in the SOW to FH. FH may subcontract work activities provided the requirements in the SOW and the FH QA Program are met by subcontractor(s).

3.2.4 Geophysics

FH is responsible for obtaining geophysical well logging services from S.M. Stoller, Inc. during drilling. PNNL provides technical support to FH to ensure that the geophysical logging requirements and associated quality requirements are specified in the SOW. The requirements for the data deliverables are also specified in the SOW. All other geophysical measurements by PNNL staff and subcontractors will be performed according to documented test procedures.

3.2.5 Field Measurements

Field measurements during well drilling will be conducted in accordance with FH procedures during well drilling, or other equivalent procedures, and as directed in the SOW. Project-specific test plans that have been reviewed and approved will address procedures during field experiments.

3.2.6 Other Services

Subcontracted services received from FH or other Hanford Site contractors may include construction of fences and enclosures, geophysical logging, etc. DOE National Laboratories and the US Geological Survey perform scientific laboratory, field, and modeling investigations as part of the Remediation and Closure Science Project.

3.3 Work Conducted by Project Staff

Analytical activities conducted by the project staff for contract releases with analytical work scope shall be conducted in accordance with written standard operating procedures. Field measurements will be

conducted in accordance with in-house operating procedures. Project staff are responsible for preparing data reports that summarize the results of analyses, quality control data for the method used and identification of data qualifiers. The results and raw data will be included in the project records.

Project staff will perform sampling and measurements according to written and approved internal procedures.

3.4 Field Work

Prior to executing field work, project-specific test plans are developed, as described in Section 5. If supplemental information or individual parameters are needed to perform a test, a test instruction will be developed. The test instruction shall be reviewed by a technical reviewer.

The Remediation Task of the Remediation and Closure Science Project uses the *Surface Environmental Surveillance Procedures Manual* (PNL-MA-580, current revision), for field work associated with task activities. The following procedures in PNL-MA-580 are used:

- Section 4.1 – Grab Samples
- Section 4.6 – Sampling Columbia River Riverbank Springs
- Section 4.8 – Specific Conductance
- Section 4.9 – pH Measurement
- Section 4.10 – Water Filtration
- Section 8.1 – Trip Sheets.

Sampling aquifer tubes will be conducted in accordance with the procedure entitled “Collecting Environmental Monitoring Waster Samples from Aquifer Tubes” (GC-3) contained in the *Procedures for Ground-Water Investigation Manual* (PNL-MA-567, current revision).

4.0 Data Quality Objectives

The QA objectives for measurements generally applicable to technology investigations under the purview of this QA Management Plan are primarily related to: (1) the definition of appropriate methods and analytical precision and accuracy appropriate for chemical analysis of the analyte of interest; and (2) the definition of methods and limits and values for physical measurements associated with the investigation (e.g., column tests). Discussions of aqueous sample analytical objectives and analytical methods with corresponding target values for detection limits, precision, and accuracy are provided in Appendix A of this QA Management Plan, the *Environmental Sciences Laboratory QA Plan* (ESL QAP, current revision), individual test plans, and/or test procedures. The sediment analytical objectives and analytical methods with corresponding target values for detection limits, precision, and accuracy are provided in the *Environmental Sciences Laboratory QA Plan*, individual test plans, and/or test procedures. DQOs developed in accordance with *Guidance on Systematic Planning Using the Data Quality Objectives Process (QA/G-4)* (EPA/240/B-06/001) will be applied. Other measurement objectives and methods with corresponding target values for detection limits, precision, and accuracy (as

applicable) are provided in the specific work plans and/or the SOW for such activities. Specific data quality needs for individual investigations that are different than the requirements established herein shall be addressed within individual work plans. Other measurement considerations, accuracy requirements, units, and data recording and reporting protocols for instruments supporting stratigraphic characterization, aquifer testing and other types of field investigations shall be as specified in the applicable plans and/or procedures.

5.0 Test Plans and Procedures

Test plans and procedures are used to assure that activities affecting quality are performed consistently and correctly. Test plans are prepared by PNNL staff to conduct a single experiment or test as identified below. Formal procedures will be developed for quality affecting work activities that are routinely performed. Additional procedures will be developed as needed.

5.1 Test Planning and Performance

Test plans will be used to document a single or related set of experiments or tests (e.g., hydrologic field tests, vertical sampling) work activity.

5.1.1 Developing the Test Plan

The test plan shall contain the following information:

- A title and/or number including date or revision.
- Dated signatures of the preparer, technical lead, Project Manager or task manager, and quality engineer.
- Individual page identification (page ____ of ____).

The content of each test plan will depend on the scope of the test. The following is a brief description of mandatory and optional items to be considered in the preparation of the test plan:

- **Purpose/Description (mandatory)** – Provide a short narrative on the purpose of the experiment/test/activity.

Example: The purpose of this test is to provide hydrologic property data at polyphosphate treatability injection test wells.

- **Prerequisites (mandatory)** – List items, conditions, or other concerns that must be satisfied prior to beginning the test.

Example: Prior to beginning the work activity, the staff must complete special training on other plans or procedures that will be used in conjunction with the test plan, special handling or storage requirements, special access or permits, and required records that need to be generated as the result of the work activity.

- **Safety (mandatory)** – Describe the hazards associated with the work such as physical agents (e.g., temperature, pressure, noise, electrical); hazardous environments (e.g., confined spaces, remote locations, heat/cold stress); and hazardous materials (e.g., flammables, corrosives, highly toxic, carcinogens). Describe the methods used to mitigate the hazards that were identified (e.g., personal protective equipment, time periods away from the hazard, alarms, location of nearest aid station).
- **Materials and Equipment (optional)** – List the materials and equipment that are necessary to complete the work.
- **Measuring and Test Equipment (mandatory)** – List the equipment that will be used to make the measurements; include the calibration requirements, system checks, and quality control checks in this section or in the work instructions section of the test plan.
- **Pretest Verification (mandatory)** – Determine if certain items of a test require verification prior to their use and indicate how the verification will be done.

Example: A tracer solution containing Br will be used throughout the test and the initial concentration shall be known. The solution shall be measured by the calibrated probe (as described above) and the concentration shall be recorded prior to injection.

- **Documentation and Reporting (mandatory)** – Describe where the data collected during the test should be documented (e.g., field record forms, laboratory record books, entered into a computer, downloaded from computer to hardcopy). Additionally, describe what will be reported, to whom, and the due date(s).
- **Work Instructions (mandatory)** – Provide step-by-step instructions and/or non-sequential instructions (whichever is more appropriate to the activity). Each step or instruction shall be as simple as possible but with sufficient detail so that individuals experienced in the technology or activity involved can easily understand. The following types of information should be considered for inclusion: administrative control hold points (i.e., where safety, quality, radiological, or other approvals or actions are required before proceeding); cautions that indicate potentially hazardous situations which, if not avoided, may result in death, injury, or damage to facilities or equipment; and notes that call attention to supplemental information that assist the user in making decisions or improving work performance.

5.1.2 Test Performance

Tests will be performed in accordance with the test plans, which shall be available at the work location. The Technical Lead is responsible for assuring that the current version is used to perform the work.

If changes to the test plan are required during the execution of the work, the Technical Lead shall document the deviation and the justification or rationale for the change.

5.2 Procedures

Procedures will be prepared, reviewed, approved, and revised in accordance with SBMS subject area, [“Procedures, Permits, and Other Work Instructions”](#) (PNNL 2004). Project staff will perform scheduling,

data verification, data processing, and data management as described in Section 6.0 and by following the applicable internal technical procedures or instructions.

5.2.1 Project Procedures

Procedures used by PNNL project staff will be developed in accordance with the SBMS subject area, “[Procedures, Permits, and Other Work Instructions](#)” (PNNL 2004). Project staff will perform scheduling, data verification, data processing, and data management as described in Section 6.0 and by following the applicable internal technical procedures or instructions. Also, project staff will perform sampling, field measurements, water-level measurements, and aquifer testing by following the appropriate internal technical procedures.

5.2.2 Water-Level Procedures

Procedures for water-level measurements shall be written in accordance with industry accepted standards, such as guidelines prepared by the U.S. Geological Survey (1977), and updated as required for the latest advances in measuring equipment.

5.2.3 Analytical Procedures

The specific work plans and/or test plans identify the constituents to be analyzed. The analytical methods required may be contained within the following references:

- *Test Methods for Evaluating Solid Waste* (EPA/SW-846, as amended)
- *Methods for Chemical Analysis of Water and Wastes* (EPA-600/4-79-020)
- *Methods for the Determination of Organic Compounds in Drinking Water* (EPA-600/4-88-039)
- *Prescribed Procedures for Measurement of Radioactivity in Drinking Water* (EPA-600/4-80-032)
- *Procedures for Radiochemical Analysis of Nuclear Reactor Aqueous Solutions* (EPA-R4-73-014)
- *Radiochemical Analytical Procedures for Analysis of Environmental Samples* (EMSL-LV-0539-17).

Analytical procedures are used to analyze for specific constituents or conduct a specialized analysis. The laboratory analytical procedures used for the Remediation and Closure Science Project are documented in Appendix B of this QA Management Plan. Analytical procedures used to support regulatory programs follow the procedures documented in the QA Plan for the Environmental Sciences Laboratory which complies with HASQARD (DOE/RL-96-68) implemented by CAWSRP located at <http://etd.pnl.gov/docs/conducting-work/index.stm>. Specific work plans and/or test plans identify the constituents to be analyzed.

Many radiochemical methods have not been standardized, but the procedures are documented in the laboratory specific standard operating procedures. Aqueous sample chemical and radiological analytical methods and requirements for constituents are specified by the SOW, work plan, or other written direction.

Most potential chemical constituents to be analyzed are provided in Appendix A, Table A.3 of this QA Management Plan and/or the *Environmental Sciences Laboratory QA Plan* (ESL QAP, current revision). Sediment and other media constituents to be analyzed and corresponding analytical methods and procedures will be passed on to the analytical laboratory by a SOW, work plan, or other written direction.

Method detection limits (MDLs) shall be determined for all non-radiochemical methods required by the project. Water MDLs shall be determined in accordance with 40 CFR 136, Appendix B “Definition and Procedure for the Determination of the Method Detection Limit—Revision 1.1.” The laboratory provides MDL studies results to PNNL as specified in the SOW. Required detection limits for radiochemical methods are provided in the SOW, work plan, or other written direction.

Sediment constituents to be analyzed for as well as the corresponding analytical methods and procedures will be passed on to the analytical laboratory by a SOW. The MDLs for sediment analysis shall be determined using the calculation provided in Chapter One of EPA/SW-846, as amended.

Technical procedures not previously documented will be developed and used as described in CAWSRP, Section 7, “Procedures.” If supplemental information or individual parameters are needed to perform a test, a test instruction will be developed. The test instruction shall be reviewed by a technical reviewer and must include the following information:

- A unique numerical designation
- Revision number
- Title
- Effective date
- Instructions - operating parameters and specific test run information such as sample size and /or composition, temperature, pH, test duration, etc.
- Reference to controlling procedure or test plan
- Approval by author
- When well-established methods (e.g. ASTM, Soil Science Society of America, or EPA) are used, a PNNL cover page will not be provided unless there is a deviation from the established method.

Appendices A and B of this QA Management Plan list additional analyses and measurements with the respective procedures, methods, and other relevant information.

Administrative quality assurance processes and procedures (e.g., chain-of-custody, custody logs, sample handling, storage and disposal, training) will be required from the onsite and offsite analytical laboratories and will be specified in the SOW.

5.2.4 Calibration Procedures

The requirements for calibrating field and analytical laboratory instruments and maintain traceability to national or international standard (e.g., National Institute of Standards and Technology) is in accordance with *Test Methods for Evaluating Solid Waste: Physical/Chemical Methods* (EPA/SW-846)

and HASQARD (DOE/RL-96-68). When subcontractors are employed these requirements are passed onto the subcontractors by a SOW. PNNL will periodically assess the use and effectiveness of procedures and systems for calibration of equipment with the subcontractors.

Measuring and test equipment (M&TE) used by PNNL staff to collect quality affecting data that are calibrated by the user (Category 2 M&TE) or by an approved external or internal sources (Category 1 M&TE) will be in accordance with SBMS subject area, “[Calibration](#)” (PNNL 2005b). Upon receiving calibrated equipment, staff must review the documentation for acceptability and verify the proper operation of the M&TE and check the calibration label.

M&TE shall be controlled as described in CAWSRP, Section 4, “Instrument Calibration,” and in accordance with the SBMS subject area, “[Calibration](#)” (PNNL 2005b). Externally calibrated measuring and test equipment (M&TE) such as balances will be calibrated per manufacturer’s tolerances unless other control limits are specified and justification is provided.

Data sheets and log book entries will be used to document pipette performance checks. Calibration reports and other calibration data will be maintained as project records.

Quality control requirements are described in CAWSRP, Section 5, “Quality Control,” and in Appendix A of this QA Management Plan. A few exceptions to CAWSRP requirements are considered necessary for the project, as described in the following paragraphs.

5.2.5 Common Data Quality Calculations

Data quality parameters of precision, accuracy, measures of agreement, detection limits/sensitivity, and uncertainty will be calculated according to the formulae in CAWSRP, Section 6, in the exhibit “Calculations for Assessing Data Quality.” For radiochemistry analyses the minimum detectable activity (MDA) is reported as the detection limit.

CAWSRP Exhibit “Calculations for Assessing Data Quality” - Control charting is a tool used to monitor an ongoing/continuous process where there are sufficient data points to perform a representative statistical evaluation. The analyses performed within this project are performed as a research function in which instrumental operating parameters may be changed to accomplish many different objectives. The frequency of instrumental operating changes does not allow accumulation of sufficient data points to properly utilize control charting as a statistical analysis tool. In lieu of control charts, instrument performance is monitored daily by the use of fixed control limits.

5.2.6 Well Drilling and Construction Procedures

FH will obtain drilling services through their procurement process. SOWs to FH specify well drilling, characterization (aquifer and sediment sampling, etc.) and construction requirements. The well drilling, sediment samples collection, groundwater samples collection, water level measurements, and notification to perform geophysical logging/gyroscope well deviation survey is the responsibility of FH. These activities will be performed to FH procedures and/or to subcontractor procedures (e.g., conducting geophysical logging/gyroscope well deviation survey). FH Health and Safety, and QA procedures and waste management procedures will be followed during the drilling activity.

5.2.7 Water and Sediment Sample Collection Procedures

Sediment and water samples collected during drilling will be collected by or under the direction of FH, and in accordance with FH or subcontractor procedures. The quality requirements for sampling activities, including chain-of-custody, storage, and records requirements are specified in the work plan or test plan.

5.2.8 Receiving and Handling Samples

Direction for sample handling and storage is provided in CAWSRP, Section 3, “Receiving and Handling Samples,” and in the SBMS subject area, “[Sample Handling, Archival, and Disposal](#)” (PNNL 2007h).

Chain-of-custody for samples will be documented using a chain-of-custody form. An example of a chain-of-custody form is provided as an exhibit in CAWSRP. Each PNNL facility is a secured area, restricted to authorized personnel only. Chain-of-custody will be documented for moving samples from one facility to another, but not for moving samples within a secured facility.

The samples to be received from other PNNL groups are materials from various field investigations. Documentation of unique sample and sub-sample identifications will be maintained for samples received from other PNNL groups and for other samples generated from tests conducted by the project. The documentation may consist of entries in Laboratory Record Books or data sheets.

Disposition of unused materials may include returning the material to another group at PNNL, the client or disposal at PNNL. Material returned to the client will be documented by a chain-of-custody. Material disposed of at PNNL will be documented by standard waste paperwork (forms). See the SBMS subject area, “[Waste, Managing](#)” (PNNL 2007j).

5.2.9 Sediment Physical Analysis Procedures

Sediment physical analyses including moisture content, particle-size distribution, hydraulic conductivity, water retention, water content, bulk density, particle density, and matric potential will be performed as directed in the test plan by PNNL staff. These procedures are contained in the internal *Procedures for Groundwater Investigations* (PNL-MA-567, current revision). For some studies, well-established methods, (e.g. ASTM, Soil Science Society of America, or EPA) are sometimes used and additional documentation is not needed unless there is a deviation from the established method.

5.2.9.1 Sediment Core Analysis Procedures

Sediment core analyses and column experiments will be performed by PNNL staff as directed in test plans. Procedures are contained in PNNL internal procedures and test plans.

5.2.9.2 Geophysical Logging Procedures

Geophysical well logging and gyroscope well deviation surveys during well drilling will be performed by S.M. Stoller, Inc., using their procedures, and as directed in the SOW. All other geophysical measurements by PNNL staff and subcontractors will be performed according to documented test procedures.

6.0 Data Generation and Acquisition

6.1 Experimental Design (Sampling Process Design)

The data generation and data collection designs for the Groundwater and Technical Integration Project experiments will be documented in individual test plans.

Sampling processes used to support the Groundwater and Technical Integration Project studies will be in accordance with the waste management area sampling design, based on the regulatory requirements (e.g., RCRA or CERCLA) and applying the DQO process in accordance with *Guidance on Systematic Planning Using the Data Quality Objectives Process (QA/G-4)* (EPA/240/B-06/001). A description of these processes will be included in test plans along with the number of samples, sampling schedule, number of sample locations, number of quality control samples (field replicates, etc.), analysis methods and quality control criteria, and the groundwater level measurements.

6.2 Sampling Methods

The procedures for collecting samples and identifying the sampling methods and equipment, including any implementation requirements, sample preservation requirements, decontamination procedures, and materials needed for projects involving physical sampling are described in the project-specific work plans and procedures. If a failure in the sampling or measurement system occur, documentation of and recovery from the failure will be documented in the project-specific laboratory record book or controlled field book. The Master Project Manager and Task Leads are responsible for ensuring that the corrective action is effective and documented.

The preparation and decontamination of sampling equipment, including the disposal of decontamination by-products; the selection and preparation of sample containers, sample volumes, and preservation methods; and maximum holding times from sample extraction to analysis will be managed in accordance with EPA/SW-846 or PNNL-specific procedures, as applicable. Waste generated as a result of the activities will be handled in accordance with the SBMS subject area, “[Waste, Managing](#)” (PNNL 2007j).

6.3 Sample Handling and Custody

Water samples will be collected in accordance with FH and/or PNNL-approved project-specific procedures. Custody of the samples in the field and receipt at the laboratory will be documented on the Chain-of-custody forms in accordance with PNNL procedures. Shipping and transporting of the samples will be handled by FH in accordance with its procedures and federal regulations. If PNNL is responsible for shipping and transporting the samples, the samples will be handled in accordance with PNNL procedures and the SBMS subject area, “[Hazardous Materials, Packaging and Shipping](#)” (PNNL 2007b).

6.4 Analytical Methods

The sampling and analysis plan for each site will identify the sample constituents and the analytical method as described in Section 5.2.3.

7.0 Data Reduction, Verification, and Reporting

7.1 Data Reduction

Data measured during technology project investigations are compiled, evaluated, and documented as described below. Verification of analytical data is performed, as appropriate, in accordance with Appendix A of this QA Management Plan. Results are reviewed to assure the reliability and validity of the field and laboratory measurements based on accuracy, precision, and detection limits. Representativeness, completeness, and comparability may also be evaluated for overall quality. These parameters are evaluated through laboratory QC checks, replicate sampling and analyses, analysis of blind standards and blanks, and/or inter-laboratory comparison. Acceptance criteria are established for each of these parameters in Appendix A of this QA Management Plan, the *Environmental Sciences Laboratory QA Plan* (ESL QAP, current revision), and/or in specific test plans. When parameters are outside acceptance criteria, corrective actions are taken to prevent a future occurrence and any data impacted is appropriately flagged.

When the data review identifies suspect data, those data are investigated to establish whether they reflect true conditions or an error. A Review Document Record (RDR) form is initiated in accordance with the procedure DA-3, "Data Review Procedure" (see PNL-MA-567) or other appropriate project-specific method.

7.2 Sample Data Tracking and Verification

The process for tracking and scheduling sampling and analysis requirements, sampling field activities, chains of custody, and laboratory analysis is managed using a variety of electronic data management tools. Groundwater data are reviewed after they are generated to assure that the reliability and validity of the field and laboratory measurements for groundwater samples collected. The reliability and validity of the measurements are based on accuracy, precision, and detection limits.

Representativeness, completeness, and comparability may also be evaluated for overall quality. These parameters are evaluated through laboratory quality control (QC) checks (e.g., matrix spikes, laboratory blanks), replicate sampling and analyses, analysis of blind standards and blanks, and inter-laboratory comparison. Acceptance criteria are established for each of these parameters in the appendix of this plan. When a parameter is outside the criteria, corrective actions are taken to prevent a future occurrence and any data impacted is appropriately flagged. Reports documenting the QC evaluation results are discussed in Section 8.0.

7.3 Sample Data and Tracking for Soil and Sediment Samples

Completed data packages for soil and sediment samples will be verified by qualified PNNL personnel. Verification will consist of verifying required deliverables for completeness, required QC results, chain-of-custody forms, and case narratives that describe any issues related to the sample analyses for all data packages. Verification may also include evaluating and qualifying results based on holding times, method blanks, matrix spikes, laboratory control samples, laboratory duplicates, and chemical and tracer recoveries, as appropriate to the methods used. No other verification/validation or calculation checks will be performed. At least 10 percent of all data types (i.e., volatile organic constituent (VOC),

semi-VOCs, metal, etc.) will be verified. Verification will be documented on checklists to be included in the project files.

7.4 Data Reporting

Data measured during the projects are compiled, evaluated, and documented as described below. When the data review identifies suspect data, those data are investigated to establish whether they reflect true conditions or an error.

Requirements for reporting analytical data are described in CAWSRP, Section 8, “Reporting Analytical Data.” All data reported shall be traceable to the M&TE and procedure (including procedure revision) or test plan used, and if the reported results are quantitative, a valid calibration. The analyst shall sign or initial and date the data reports unless the results printed by the instrument include identification of the analyst and date. A staff member other than the person who performed the work, and who is knowledgeable in the area being reviewed, shall review the data before results are reported.

Interpretative data, test results, and reports will be released through the information release process in accordance with the SBMS subject area, “[Publishing Scientific and Technical Information](#)” (PNNL 2007d).

Seismic data are reported in three (3) quarterly reports and an annual report published by PNNL. These reports will be released through the information release process in accordance with the SBMS subject area, “[Publishing Scientific and Technical Information](#)” (PNNL 2007d).

Project summary reports (e.g., Borehole Data Package Report, Cumulative DPT Analytical Report, Tier I Sample Analysis Report, etc) will be generated after the completion of each scope phase. These reports will be released through the information release process in accordance with the SBMS subject area, “[Publishing Scientific and Technical Information](#)” (PNNL 2007d).

8.0 Analytical Quality Control Checks

Analytical QC checks are performed on internal and external samples. A summary of QC check samples is outlined in Appendix A of this QA Management Plan, the *Environmental Sciences Laboratory QA Plan* (ESL QAP, current revision), and/or in specific test plans. Internal QC data are generated when the analytical laboratory prepares QC samples to monitor the quality of their analyses.

The QC activities needed for sampling, laboratory (internal and external) and field analysis, or measurement technique will be defined in the appropriate project test plans. For each required QC activity, the associated method, acceptance criteria, and corrective action will be listed. Also, for the field and laboratory QC activities included, but not limited to, are the use of blanks, duplicates, matrix spikes, laboratory control samples, and surrogates in the plans.

9.0 Assessments

Assessments are performed to gather results that can be evaluated to measure the effectiveness of the quality systems and processes implemented by the project. Assessments will be performed periodically during the year. The following types of assessments may be used at varying frequencies during the year:

- Management self-assessment — an assessment performed by those immediately responsible for overseeing and/or performing the work to establish whether policies, practices, and procedures are adequate for assuring results needed.
- Management independent assessment — an assessment performed by an individual or group independent of the work performed to assure that policies, practices, and procedures are adequate for assuring results needed.
- Technical independent assessment — an assessment performed by an individual or group technically competent to do the work but independent of the work being performed to assure qualitative and quantitative aspects of the work are accomplished according to documented specifications.

Data quality assessments are conducted as project quality control checks. The focus of data quality assessments is independent verification of reported results. Data quality is routinely evaluated through technical review. If the complexity and/or significance of the work performed warrants it, the Project Manager will direct the quality assurance representative and/or another staff member to conduct an additional quality assessment. The assessment is documented and retained in the project records. Documentation of the above assessments as well as any external assessments performed is maintained as project records. The Project Manager is responsible for ensuring that any deficiencies are corrected in a timely manner.

9.1 Assessment Planning and Documentation

Assessment planning is done by the project management team (including Project Manager, Task Leaders, Principle Investigator, and appropriate staff) in consultation with the project Quality Engineer. Assessments are in accordance with the SBMS subject area, “[Planning, Assessment, and Analysis](#),” Section 2, “[Performance Assessment](#)” (PNNL 2007c). An assessment schedule for the year is developed. The assessor plans the assessment on a Self-Assessment Planning Form (see example in Figure 9.1) where the scope of the assessment, topic and supporting references are documented on the plan. A unique identification number is assigned to the plan and entered on an Assessment Log Sheet. The Project Manager (or delegate) approves the plan.

Results of assessments will be documented on a Self-Assessment Results form (see example in Figure 9.2). The corrective action and action owner will be documented on the assessment report. The Task Manager will assign the action owners, and the Project Manager will prioritize the corrective actions. An action item log will be maintained by the project Quality Engineer to track and close out actions, and to finally verify the corrective actions. The Project Manager will sign the assessment report when the corrective actions have been closed. The assessment plan and report will be distributed to the appropriate Task Managers, Project Manager and project records.

SELF-ASSESSMENT PLANNING FORM

Scope & Location: <i>(General: Maintenance, Operations,</i>	I.D. Number: <i>(ATS Number or other Unique Tracking Number)</i>
Topic: <i>(Describe what will be assessed)</i>	Date: <i>(Date planning form is prepared)</i>
References: <i>(Cite Source Documents for Performance Expectations i.e., Regulation, Environmental Permit, DOE Order, A-Manual, Standards Based Management System [SBMS], Requirements, Procedures and Guidelines [RPG]).</i>	

Performance Expectations

Criteria developed from Source Documents that will be applied throughout the assessment. Each criteria/expectation will have the reference enclosed in parenthesis at the end of the criteria/expectation statement (e.g., DOE Order 5480.19, SBMS, RPG). Performance expectations should be limited to six maximum to allow the assessment to remain focused. Additional Planning Forms can be completed to expand the scope of a particular assessment.
1.
2.
3.
4.
5.
6.

Procedure: <i>(Perform the following as applicable for the assessment)</i> Review assessment planning form <ul style="list-style-type: none"> • Review applicable procedure/requirements. (references) • Conduct performance tests and data validation. • Observe the activity controlled by the procedure. • Interview appropriate personnel about requirements and practices. • Record observations based on comparison to plan. • Document the results after receiving final information on the Self-Assessment Results form.

Basics for the <input type="checkbox"/> Planned <input type="checkbox"/> Lessons Learned Assessment: <input type="checkbox"/> Responsive <input type="checkbox"/> Other Work Package Number (optional): Assessment Requestor/Authorizing Person: Assessor(s):
--

Figure 9.1. Self-Assessment Planning Form

SELF-ASSESSMENT RESULTS

Assessor:	I.D. Number:
Assessment Location:	Date: <i>(Date assessment performed)</i>

Results

(Related to Associated Performance Expectations)

(Use additional pages if necessary.) Concise and objective statements are the goal. Subjective comments may be added at the end and must be based upon a series of facts that supports the comments. Include strengths and improvement opportunities. Include date the information is obtained and list of line manager or points-of-contact during assessment.

Summary

1.

2.

3.

4.

5.

Subsequent Actions

(Related to Associated Results)

Assigned Action	Action Owner	Due Date
1.		
2.		
3.		
4.		

Actions Assigned By:

Date:

Completion *(To be signed by Lead Assessor when assessment is completed.)*

Signature:

Date:

Completion *(To be signed by Manager when assessment is completed and all actions have been entered into ATS)*

Signature:

Date:

Figure 9.2. Self-Assessment Results

9.2 Subcontractor Collaborator Assessments

If PNNL passes work to subcontractors, periodic assessments of these subcontractors are performed as an oversight function or prior to contract award in accordance with the internal acquisition quality procedures. Provisions are made in the SOW for oversight assessment activities to be performed as necessary.

The results of all subcontractors' assessments (including surveillances and audits) will be made available to project and line management, individuals contacted, and the client as requested. The corrective action tracking, corrective action and closure response will be in accordance with the internal acquisition quality procedures. The official assessment report files and responses (audits and surveillances) are maintained in the PNNL Suppliers History File by the Quality Assurance Services group.

Periodic assessments of the well drilling and construction, drilling and sampling-related activities, and the Environmental Sciences Laboratory may also be performed in accordance with the requirements discussed above.

10.0 Preventive Equipment Maintenance

Subcontracted organizations will be required to implement preventive maintenance of their equipment to mitigate the possibility of down time affecting cost and schedule. This will be specified in the SOW to the respective organizations.

11.0 Specific Routine Procedures Used to Assess Data Precision, Accuracy, and Completeness

The evaluation of laboratory precision, accuracy, and completeness is accomplished during the verification process performed upon receipt of data (see Section 7.0 of this plan).

12.0 Corrective Action

12.1 Project Corrective Actions Resulting from Assessments

As part of the continuous improvement processes initiated by the project management team, assessments will be tracked and improvement actions identified and prioritized. The [Assessment Tracking System \(ATS\)](#) is the process used by this Master Project for tracking and managing assessments, including determining Conditions and the development of actions. ATS supports the identification, control, and correction of items, services, and processes that do not meet established requirements. The SBMS subject area, "[Assessment Management](#)" (PNNL 2005a) documents this

corrective action management process for handling and documenting events and assessments, including those which must be tracked in ATS such as formal project reviews or audits performed by the client or their representative; management-initiated assessments; etc. If immediate corrective action is required, the quality problem will be directly entered into the Assessment Tracking System (ATS) and actions taken as specified in Section 11.2.

12.2 Unplanned Deviations

Corrective action must be initiated by the Project Manager or cognizant task manager when unplanned deviations from procedural, contractual, regulatory requirements, or construction specifications occur. These deviations will be documented by documenting the quality problem information directly into the ATS in accordance with the SBMS subject area, "[Quality Problem Reporting](#)" (PNNL 2005c). The assessment must describe the problem, the cause of the deviation, the impact of the problem, and corrective action needed to remedy the immediate problem and to prevent recurrence.

Subcontractors will be required to have systems in place to identify, correct and prevent recurrence of contractual, procedural or regulatory requirement(s) deviations, and to notify the PNNL point-of-contact specified when such an event occurs. These requirements will be passed on in a SOW to the subcontractors.

12.3 Planned Deviations

Planned deviations from procedure, documented (including justification) and approved by the Project Manager or Task Leader in advance, do not constitute a deficiency and do not require generation of an assessment item. Documentation may consist of a hard copy e-mail or memo to the Project Manager or Task Leader. This documentation must include either an approval signature if on a memo or electronic approval via a reply to the e-mail indicating such approval.

12.4 Measuring and Test Equipment Calibration Discrepancies

Subcontractors will be required to maintain a system for identifying calibration discrepancies and tracing data or samples that may have been affected. Subcontractors will be required, via their SOW, to notify the PNNL point-of-contact as soon as possible when such an incident occurs. PNNL will perform periodic assessments to assess the effectiveness of subcontractor procedures and processes for calibration control.

Project staff must investigate instruments or equipment found to be operating outside acceptable operating ranges (as specified in the applicable technical procedure or manufacturer's instructions) and issues must be addressed in accordance with the SBMS subject area, "[Quality Problem Reporting](#)" (PNNL 2005c). When as-found data on an instrument's calibration report was found to be "Out of Tolerance" during the review and acceptance process of the contract supplier documents submitted in response to quality requirements, an "Out-of-Tolerance Notification will be generated using the ATS in accordance with the SBMS subject area, "[Assessment Management](#)" (PNNL 2005a). Then the project staff must determine if there was any impact on data. When Category 2 M&TE are out of tolerance, proceed with the evaluation to determine impact on data and document the results with justification in the ATS.

13.0 Quality Assurance Reports to Management

Quality activities such as project improvement efforts, significant deficiencies identified and the associated corrective actions, and summary of assessment results will be reported to the Project Manager. When major quality problems are identified, they shall be reported to the Project Manager. Surveillance plans and results of the surveillances are provided to the Project Manager and Task Manager after a surveillance event.

Quality-related problems identified by project personnel must be reported to project management immediately for resolution. Any problems involving data quality, sample integrity, or test measurements will be thoroughly documented by a Problem and Discrepancies form and communicated to the appropriate Task Leader and Project Manager for resolution.

Significant quality-related problems that may affect customer satisfaction shall be communicated to the Product Line Manager by the Project Manager.

14.0 Records

14.1 Records Control

The SBMS definitions of project records and record material apply to this project. As stated in the SBMS subject area, “[Records Management](#)” (PNNL 2007f), project records are any recorded information relating to a specific research project. Record material includes information, regardless of its media (e.g., hard copy, electronic, microfilm), created or received in connection with Pacific Northwest Division business or research activities that documents research and administrative functions, policies, decisions, procedures, operations, or other activities, and which is preserved for its value.

NOTE: E-mail that is record material must be printed out and maintained as the record copy unless the email is put directly into the PNNL [Total Records Information Management \(TRIM\)](#) System.

Record material that is not stored in Field Notebooks or Laboratory Records Books (see Section 19.5 of this QA Management Plan) or is not electronic data gathered from sensors or instruments in the field and/or lab (see Section 14.3 of this QA Management Plan) such as project-specific field data forms, shall be scanned and managed as pdf files in accordance with Section 14.3. The record material shall be scanned and archived at least quarterly or more often, such as weekly or monthly, if the accumulation of the material is significant and inadvertent damage or loss would cause irreparable damage to the project.

Records that document the sampling subcontractor activities, analytical results, verification and compliance checks, quarterly and annual reports, test plans and associated results, groundwater monitoring plans, and assessment reports will be maintained as project records. Individual monitoring plans and work plans may identify other records requirements. Project records will be legible, identifiable and maintained in accordance with the PNNL SBMS subject area [Records Management](#) (PNNL 2007f). Test results documented in laboratory record books will be reviewed semi-annually by a

technically qualified individual who did not perform the work. The reviewer will verify that there is sufficient detail to retrace the investigation and confirm the results.

The project records specialist prepares and submits a Records Inventory and Disposition Schedule (RIDS) File Index for review and approval by the records management representative and Quality Engineer. The records custodian reviews and updates the RIDS annually at a minimum, or when a major change to the program occurs. Records retention schedules shall be based on requirements of the TPA (Ecology et al. 1989), which requires the retention of records for 10 years after termination of the TPA.

14.2 Records Transfer to Storage

On an annual basis, the records custodian will transfer to storage inactive records as identified by the project staff as not required for day-to-day operations. Sampling and analysis plans, assessments, and special project correspondences will be maintained by the project until the completion of the activity or project. The project records specialists generates the internal form (e.g., [Records Transfer Data Input \[RTDI\] Form](#)). The records management representative will sign the RTDI form as acknowledging receipt of the records and return a copy of this form to the records custodian. The RTDI form is then placed in project records.

Within 90 days of project completion or termination, records shall be transferred to storage and/or the client. The project records specialist completes the appropriate internal form (e.g., [Records Transfer Data Input \[RTDI\] Form](#)). The records management representative will sign the RTDI form as acknowledging receipt of the records and return a copy of this form to the records custodian. The RTDI form is then placed in project records.

14.3 Electronic Data/Records Management

Electronic data gathered from sensors or instruments in the field and/or lab will be maintained and managed appropriately to allow for reproducible results. Electronic data that are directly delivered and/or used in analysis, and is delivered to the customer, will be maintained as project records, in accordance with the requirements of the SBMS subject area, "[Records Management](#)" (PNNL 2007f).

Electronic data produced by instrumentation or sensors are usually stored on that instrument and are only usable by the system itself. It is necessary for the electronic data to be transferred, without error, to a form which can be used by a variety of software applications. An example would be to transfer an ASCII file into a Microsoft Excel® file.¹ To ensure that the data transfer process has occurred in an acceptable manner, a review of a representative sample, of sufficient data points to provide confidence that the data have been transferred properly, shall occur. The review method used and results obtained shall be documented and retained as project records in the Laboratory Record Book, in accordance with section 19.5 of this plan. For retrieval of the data, the staff member shall record the use of the data on the media used to store the raw data and in the project records. The staff member shall ensure that unauthorized modifications are not made to the data during its use. The method of control shall be documented in the project records by the staff member. The staff member shall ensure that a back-up of the data is maintained in the project records. The use of the data in software applications shall be documented, along with the software application name and version number.

¹ Microsoft Excel is a registered trademark of Microsoft Corporation.

Electronic data shall be archived and saved as project records based on the project's record retention period. When the project records are required be maintained for a minimum of 10 years, after the close of the project, saving the raw electronic data files to a CD/DVD is sufficient. When the project's record retention requirements are longer than 10 years, the raw data files should be saved either to magnetic media (TRIM, tape) or optical media (CD, DVD). The [Total Records Information Management \(TRIM\)](#) system is one option for storing raw data files and is approved for projects that have a permanent retention period.

Backup and archive processes shall be followed for maintaining the data during the life of the project. Electronic data backups shall be performed every night, in accordance with the requirements identified by the PNNL IT Computing Services - [InfoSource](#) website. The computer backup procedures identified on the PNNL Infosource website for [Data Backup Options](#) shall be followed based on the type of computer or server on which the data are stored. The data backup process is identified below:

14.3.1 Workstations

PNNL staff members are responsible for making sure the data on the computers they use are backed up regularly. There are three (3) options for backing up these data:

1. The staff member can sign up for one of the PNNL [workstation backup and restore \(WBR\)](#) services: [WBR Connected DataProtector](#) for Windows[®], [WBR Mac](#) for Macintosh[®], or [WBR Networker](#) for all other systems.^{2,3} WBR is free to each staff member for one workstation. Additional backup subscriptions are available for a small monthly fee. (See the WBR website for restore instructions.) The maximum backup size is 100 GB for Windows workstations.
2. A [network shared folder](#) may be used to store files on a PNNL network file server. Network shared folders are backed up nightly. To retrieve files from a backup, request a file restore by calling the PNNL Help Desk at 375-6789 or [sending them email](#). They will need the complete name of the shared folder (for example, [\\pnl10\projects](#)) and the name and date of the file or directory that needs to be restored.
3. Manually copy files to floppy disks, CDs, or DVDs. Most computers purchased through MHP come with large-capacity floppy drives, CD-RW drives, and/or DVD drives. A CD can hold 600MB or more; DVDs 4.7 GB. Either of these methods is suitable for backing up important data files, but not recommended for backing up the entire system.

14.3.2 Servers

The data backup options for servers include the following:

1. The Workstation Backup and Restore (WBR) service. For a small monthly fee, WBR performs a full backup of all the project's programs and data. (See the WBR website for restore instructions.)
2. Backing up to Zip disks or to a tape drive connected to the server. If a tape drive connected to the project server is used, refer to the manufacturer's instructions for setting up backup schedules and performing restores.

² Windows is a registered trademark of Microsoft Corporation.

³ Macintosh is a registered trademark of Apple, Inc.

Archives of the data shall occur at least every two (2) weeks. It is recommended that this occur at least once a week. The electronic data shall be archived to a CD/DVD and kept in the project working files until the electronic data are no longer being used, at that point the electronic data shall be moved to TRIM when longer storage retention is required by the records requirements.

15.0 Procurement Control

Project staff procuring quality affecting materials (e.g., calibration standards, chemicals) or services (e.g., calibration, analytical services, or other subcontracts for technical services) will be obtained in accordance with the SBMS subject area, “[Purchasing Goods and Services](#)” (PNNL 2007d). For this project, the majority of procurements will result in purchases of services such as drilling, sampling, and analysis. All procurements will be obtained in accordance with SBMS subject area, “[Purchasing Goods and Services](#)” (PNNL 2007d). SOWs for purchasing services shall be reviewed and signed by the project Quality Engineer to assure consistency of quality assurance requirements specified to subcontractors with project quality standards in this plan.

15.1 Sample Collection and Handling

Test plans used for field experiments will include requirements for sample collection, sample handling, sample labeling, custody of the samples in the field to delivery to the laboratory or shipper, and water level measurements. The test plan procedure will pass on the requirements of the *EPA Requirements for Quality Assurance Project Plans (QA/R-5)* (EPA/240/B-01/003) and HASQARD. A review must be performed by the Quality Engineer during the planning stages and preparation of the test plan procedure.

15.2 Groundwater and/or Sediment Analytical Measurements

If the groundwater or sediment analysis will be conducted by subcontractors or collaborators on the project, requirements will be specified in the SOW or Letter of Instruction (LOI) as applicable. The LOI is the mechanism to be used for work requests to other Hanford Site contractors. An LOI or SOW must accompany each purchase order. A review must be performed by the Quality Engineer during the planning stages and preparation of the SOW/LOI. The SOW must define the data quality and any additional project requirements associated with the service requested. The data quality requirements should include a description of the QC samples for each analysis for determining the level of possible contamination from preparation and analysis. The project requirements should include information on analysis method, calibration standards traceable to the National Institute of Standards and Technology (NIST), sample turnaround time and reporting requirements, and disposal requirements for remaining sample material and the waste from the process. The LOI/SOW will pass on the requirements of the *EPA Requirements for Quality Assurance Project Plans (QA/R-5)* (EPA/240/B-01/003) and HASQARD to the analyst.

15.3 Other Hanford Contractor Services

Other Hanford contractor services (e.g., well drilling and construction) will be obtained using the procurement process. An electronic requisition will be generated by project staff accompanied by a work

authorization document (LOI or SOW). The work authorization document will describe the requirements for the requested services. The SOW will pass on the requirements of the *EPA Requirements for Quality Assurance Project Plans (QA/R-5)* (EPA/240/B-01/003) and HASQARD to the subcontractor. A review must be performed by the Quality Engineer during the planning stages and preparation of the SOW/LOI.

15.4 Technical Services from Subcontractors

Technical services from subcontractors will be procured by using a work authorization document (LOI or SOW) accompanied by a work package authorization (WPA) or work orders. A review must be performed by the Quality Engineer during the planning stages and preparation of the SOW/LOI. The work authorization document must define the data quality and any additional project requirements associated with the service requested. The data quality requirements should include a description of the QC samples for each analysis for determining the level of possible contamination from preparation and analysis. The project requirements should include information on analysis method, calibration standards traceable to the National Institute of Standards and Technology, sample turnaround time and reporting requirements, and disposal requirements for remaining sample material and the waste from the process. The SOW will pass on the requirements of the *EPA Requirements for Quality Assurance Project Plans (QA/R-5)* (EPA/240/B-01/003) and HASQARD to the subcontractor. Where software is involved, DOE Order 414.1C requirements will be passed on to the subcontractor.

16.0 Staff Training

Staff performing activities affecting quality shall be issued documented training assignments including applicable project administrative and technical procedures and this plan.

1. Project manager and staff members will assess project specific training needs. The assessment will include evaluating cumulative training records of the staff.
2. Project manager will assign reading and/or briefings of procedures as needed. If training is assessed and the need for formalized training identified, the staff member will be scheduled to attend a formal training class.
3. Training will be documented on either a Briefing Document, or an individual On-the-Job Training (OJT) or Reading Assignment Documentation form, or a Group OJT or Reading Assignment Documentation form. These forms are available internally to PNNL staff. Documentation shall be sent to the PNNL Laboratory Training Coordinator for input into the training database. The training database will contain the record copy of project staff training.

The project shall utilize personnel who are knowledgeable and possess adequate technical, managerial or professional skills to perform all their assigned tasks. The Project Manager will identify any additional specific project-related processes that will require the project staff training and qualification and who will be responsible for assuring the project-specific training will be developed, delivered, and changes managed in accordance with the SBMS subject area, "[Training Design, Development, Implementation and Evaluation](#)" (PNNL 2002a). The project shall maintain training documentation for project-required coursework or on-the-job training taken by staff that is not capable of being tracked in the Laboratory's training database in accordance with the SBMS subject area, "[Training and Qualification for Staff and Non-Staff](#)" (PNNL 2005d).

The Project Manager, or delegate, shall inform the immediate manager of project staff of the requirement to take project required training and assure that the training has been completed prior to project staff conducting work that requires the training. The immediate manager of project staff, or their delegate, shall record the need for identified project required training and assuring training (and retraining for changes) records (for both Lab-level and project -specific training) will be maintained in accordance with the SBMS subject area, "[Training and Qualification for Staff and Non-Staff](#)" (PNNL 2005d).

The development of software products that require complex or unfamiliar interactions with users and operators should include a comprehensive plan for training. The training plan should include the following:

- a. A description of the populations to be trained, the training objectives for each population, and the content to be covered in the training
- b. An estimate of the amount of resources necessary for training development, delivery, and time expenditures
- c. Procedures for evaluating the effectiveness of the training and for making modifications to the training.

The master Project Manager has identified the following project specific training requirements on which the project core team members will have been briefed:

- The Project Management Plan
- Appropriate QA plan(s)
- Health and Safety Plan.

The individual projects shall maintain training documentation for project-required coursework, or on-the-job training taken by staff, which is not capable of being tracked in the Laboratory's training database in accordance with the SBMS subject area, "[Training and Qualification for Staff and Non-Staff](#)" (PNNL 2005d).

17.0 Software Control

Various tasks of the project require the use of databases and software, which are managed, controlled, and operated by entities that are outside PNNL. The project also requires the use of databases and software that are developed, managed, controlled and operated by PNNL. A graded approach is used to establish software quality assurance requirements based on identified risk. Software QA at PNNL is based on DOE Order 414.1C, *Quality Assurance*. This order establishes specific requirements for software related to safety and nuclear facilities.

The project uses databases, custom applications, and configurable software to support various activities. These databases, custom applications, and configurable software (spreadsheets, and queries) used to generate reportable results shall be documented in accordance with the SBMS subject areas, "[Safety Software](#)" (PNNL 2007g) or "[Software](#)" (PNNL 2007i). This documentation is maintained in project files.

17.1 Software and Software Applications

“Software” is defined as computer programs – including computer programs embedded in firmware (see the SBMS subject areas, “[Safety Software](#)” [PNNL 2007g] or “[Software](#)” [PNNL 2007i]). Software that is an integral part of firmware or equipment, where all software maintenance is performed by the vendor and the software is verified as an integral part of the system (e.g., calibration with known standard materials), is excluded. Any vendor will be required to follow the NQA-1-2000 standards for software when the software that is part of firmware is identified as Safety Software. The Safety Software clause ([QA-197a](#)) will be passed down in any SOWs, at a minimum, and possibly with additional clarification, when requested by the vendor when the work being done is identified as safety software. The Software clause ([QA-197b](#)) will be passed down in any SOWs, at a minimum, and possibly with additional clarification, when requested by the vendor for non-safety applications being developed.

All software applications used for the projects under this plan will be reviewed and identified as Safety Software or Software when the results from the software application are part of the deliverable to the client. The grading process for Safety Software will be recorded and copies for each application will be maintained as project records for each project that falls under this plan. Software applications that will follow this plan have the potential to be identified as Safety Software and when graded as such, will follow the “[Safety Software](#)” (PNNL 2007g) Level C requirements, at a minimum as identified in SBMS. The SBMS subject area, “[Safety Software](#)” (PNNL 2007g) is based on DOE O 414.1C, which includes the NQA-1-2000 standard.

If applications are not identified as Safety Software, they will be documented as Software and the documentation will be maintained as project records. Safety Software and Software applications identified for the projects in this plan will perform the work activities identified below that pertain to Custom Developed, Configurable, Acquired/Legacy, Utility Calculations and Commercial Design and Analysis Software.

All Safety Software applications are required to be identified in the Information Resource Inventory ([IRI](#)). All Safety Software will be identified as Safety System Software, Safety and Hazard Analysis Software and Design Software, or Safety Management and Administrative Controls Software. The following will additionally be identified for each software application in the IRI: Type of software, graded level, version of the software and the scope of the software, for the intended use with the project. The owner and point of contact information will also be identified in the IRI.

17.1.1 Minimum Documentation Requirements

To ensure that the implementation of the software satisfies requirements, the following documentation is required as a minimum for all Safety Software applications. These document requirements must be reviewed, approved, and processed through ERICA for software code being developed as a deliverable. The rigor of the documentation will be decided based on the grading of the safety software application. Refer to the [SQA Activity Tailoring](#) exhibit, in the SBMS subject area, “[Safety Software](#)” (PNNL 2007g) for guidance on the rigor needed for the documentation requirements. The document requirements will be for each document identified below. The document requirements may be grouped together in one document or may be separated into separate documents identified below:

- a. Software Requirements Specification (SRS)
- b. Software Design Description (SDD)
- c. Verification and Validation Plan (VVP)
- d. Verification and Validation Report (VVR)
- e. Configuration Management Plan (CMP)
 - 1) A problem reporting and corrective action tracking system will be identified with the Configuration Management Plan documentation.
 - 2) Data management process will also be identified, when applicable
- f. Procurement Contractual documentation, when applicable.

17.1.2 Software Requirements Specification

The software requirements specification (SRS) shall clearly and precisely describe each of the essential requirements (functions, performances, design constraints, and attributes) of the software and the external interfaces. Each requirement shall be defined such that its achievement is capable of being objectively verified and validated by a prescribed method (e.g., inspection, analysis, demonstration, or test).

The software requirement specification is subject to the Software Requirements Review (SRR), identified in applicable Configuration Management Plans when needed, which identifies the quality assurance aspects of work activities.

17.1.3 Software Design Description

The software design description (SDD) shall depict how the software will be structured to satisfy the requirements in the software requirements specification. The design document shall describe the components and subcomponents of the software design, including data bases and internal interfaces and is a technical description of how the software will meet the requirements set forth in the requirements specification. Its most important function is to describe a decomposition of the whole system into components (subsystems, segments, etc.) that are complete and well-bounded. In addition, it should document the rationale for the more important design decisions in order to facilitate the understanding of the system structure.

The software design description will document major system features such as data bases, diagnostics, external and internal interfaces, as well as the overall structure of the design. It involves descriptions of the operating environment, timing, system throughput, tables, sizing, centralized or distributed processing, extent of parallelism, client/server, reusable objects library, program design language (PDL), prototypes, modeling, simulation, etc. The design description will also document any input and output data that may be required. The quality assurance organizational element can observe demonstrations, which is a more efficient way to review and assess written design documentation.

The software design description will be updated after each significant review. A new version containing a more detailed design description is developed for each subsequent review.

17.1.4 Verification and Validation Plan

The verification and validation plan (VVP) shall identify and describe the methods (for example, inspection, analysis, demonstration, or test) to be used:

1. To verify the following:
 - requirements in the software requirements specifications have been approved by staff with appropriate authority
 - requirements in the requirements specifications are implemented as described in the software design description
 - design documented in the software design description is implemented in the code.
2. To validate that the code, when executed, complies with the requirements expressed in the requirements specification.

The verification and validation plan describes the overall approach for verification and validation of the software or modeling approach and will be produced and reviewed incrementally, for Safety Software applications. The tasks, methods, and criteria for verification and validation will be described in the appropriate verification and validation plans for each application.

The verification and validation plan will be used for documentation of the testing standards and practices as they are defined in the plan for each application. The verification and validation plan will document the scope of the validation testing to ensure the baseline requirements and explain the stages of development that require customer review and the extent of the verification that will precede such a review.

The verification and validation plan will specify minimum test documentation requirements for each test performed. Additionally, a section of the each plan will identify a verification matrix where the requirements are listed with their corresponding test. A matrix will be maintained during the life of the software and will be used to verify all the requirements have been met, identified, and tested.

The contents of the verification and validation plan will be evaluated at a Verification and Validation Plan Review prior to testing. Such a review will be conducted when significant changes are made to the baseline. The Verification and Validation Plan Review will be used to identify all changes to be tested and to pass on pertinent information to the appropriate testing staff.

17.1.5 Verification and Validation Report

The verification and validation report (VVR) shall describe the results of the execution of the Verification and Validation Plan Review. The report summarizes the observed status of the software as a result of the execution of the verification and validation plan. The report should include the following information:

- a. Summary of all life cycle verification and validation tasks
- b. Summary of task results
- c. Summary of anomalies and resolutions

- d. Assessment of overall software quality
- e. Summary from the verification matrix
- f. Recommendations such as whether the software is, or is not, ready for operational use.

The report may be a full report or a summary (depending upon the grading of the software).

17.1.6 User Documentation

User documentation will be developed for applications where the code is part of the deliverable.

17.1.7 Configuration Management Plan

The Configuration Management Plan (CMP) shall document methods to be used for identifying software items, controlling and implementing changes, and recording and reporting change implementation status. The Configuration Management Plan should describe the tasks, methodology, and tools required to assure that adequate configuration management procedures and controls are documented and are being implemented correctly. If the Configuration Management Plan is not a stand-alone document, and is included in the QAPjP or PMP, it is not necessary that the quality assurance organizational element prepare it; however, it is essential that one exist for each project or set of applications under each project.

The Configuration Management Plan should describe the methods to be used for

- a. Identifying all the configuration items (each software item will be identified if it is considered to be Safety Software or not, if identified as Safety Software, the level will be identified as well)
- b. Controlling and implementing changes
- c. Recording and reporting change and problem reports implementation status
- d. Conducting configuration audits
- e. Identifying review and approval cycle as well as signature authority
- f. Identifying the personnel responsible for maintaining the baselines and distributing the plan.

The Configuration Management Plan shall contain the information identified in the SBMS subject area, “[Safety Software](#)” (PNNL 2007g) for the appropriate level of software to which the application was graded. Most software application for the work under this project will be graded at Level C.

17.2 Software Use in Analysis

The use of software of any kind to conduct analyses delivered, or in support of a deliverable, to the customer includes data analysis tools such as spreadsheets and statistical analysis software, databases, modeling and simulation tools. Excluded are software productivity tools such as word processors and spreadsheets when no automated calculations, macros, or scripts are used. The projects under this plan shall conduct work in accordance with requirements for the control of software used in analyses as defined in the SBMS subject area, “[Safety Software](#)” (PNNL 2007g) or “[Software](#)” (PNNL 2007g) based on how the software being used is graded.

17.3 Utility Calculations

The purpose of this section is to define a uniform method for documenting the quality controls in place when using software packages (e.g., Excel, Mathematica[®], Matlab[®], Mathcad[®], etc. known as Utility Calculations) for calculations that are a significant part of a client deliverable, but not classified as Safety Software.^{4,5,6} As stated above, the Safety Software classification involves software failure that could result in the loss of life or serious injury, exposure to hazardous materials in excess of standards, serious damage to the environment, or noncompliance with laws or regulations.

Excel or other Utility Calculation analyses that are not used for a significant part of a client deliverable or are only used as a double check are exempt from these instructions. These instructions apply to the use of scripts and/or macros, within Excel, as well as Excel basic calculations. Portions of this project that have been identified as containing Safety Software must to follow the [Utility Calculations Guidance](#) identified in the SBMS subject area, “[Safety Software](#)” (PNNL 2007g). For additional information, refer to the SBMS “[Software](#)” subject area, [Section 11 – Using Software to Conduct Analysis](#).

NOTE: Excel is used as the example in these instructions; however, the process is the same for all other Utility Calculations.

These requirements and instructions apply to Project Managers and staff who will use Excel to conduct analysis to be delivered to the client, or to conduct analyses in support of a deliverable to the client. The process shall be implemented as follows:

- **Requirements and Risk Identification:** Plan out the analysis that will be performed and assess the risk associated with the failure of the software. Document the associated risk and the analysis to be performed (this could be one (1) paragraph in a Microsoft Word[®] document or on another tab in the Excel spreadsheet itself).⁷ (See risk examples in Table 17.1)
- **Design and Validation Planning:** Prepare and document how the Excel file will be validated/reviewed and tested by an independent technical reviewer. Identify and document who will perform the independent technical review. (Identify what the problem is that is trying to be solved and what actual calculations are being performed to solve the problem. This information will be useful for the independent technical reviewer. This could be one (1) paragraph in a Word document or on another tab in the Excel spreadsheet itself.)
- **Implementation:** Conduct the analysis using the Excel spreadsheet with the appropriate calculations based on the planning previously performed. (If the implementation of the analysis has changed, go back and update the risk associated with the analysis and the documentation to be used for the validation, if applicable)
- **Verification:** Review/verify the results of the analysis. Review the results produced from the analysis. Determine if the analysis and results support the problem that is trying to be solved. Document the verification/review step. (Documenting this step can be done with one paragraph

⁴ Mathematica is a registered trademark of Wolfram Research, Inc.

⁵ Mathcad is a registered trademark of Parametric Technology Corporation

⁶ Matlab is a registered trademark of The MathWorks, Inc.

⁷ Microsoft Word is a registered trademark of the Microsoft Corporation.

in a Word document or on another tab in the Excel spreadsheet itself, of what was reviewed and identify if the outcome was acceptable or if additional work needs to be done.

- **Validation:** Conduct independent review of results and validation. Provide the identified independent technical reviewer the Excel spreadsheet and Word document, if applicable. (the reviewer needs to have all the information regarding the requirements, risk, design and review expectations to perform the review)
- **Independent Technical Review:** Reviewer performs the review, per the instructions provided, and documents any additional checks performed on the file that extended outside the original scope of the review and the method used to perform the review of the results. The reviewer documents the outcome of the review. (the documentation can be one (1) paragraph in a Word document or on another tab in the Excel spreadsheet itself)
 - The results shall be determined based on using an alternate method to perform the analysis. Typical alternate methods include: literature review, empirical data, hand calculations, executing the analysis on a comparable but different tool.
- **Documentation:** Print the Excel spreadsheet with the analysis/results and attach the Word document or the tab in the Excel spreadsheet itself that contains the identified requirements, risk, design, validation steps, verification and independent technical review steps and results. Have the independent technical reviewer sign the document. The verifier needs to sign the verification step. Place this signed document in project records.

Table 17.1. Software Risk Management Examples

Identified Risk	Overall Risk to Project	Preventive Action	Contingency Action	Trigger	Owner
Changing requirements after starting design/development.	Medium	Customer approval of requirements before design/development, flexible design and CM process.	Changes affect either schedule or resource allocation.	Customer request.	Battelle / Customer
Incomplete input data.	High	Identify appropriate sources of validation data.	Manual updates to input tables are tracked through the change control process.	Appropriate input tables not available.	Battelle / Customer
Change in project budget or/or schedule.	Low	Define and implement new process.	Continue current process.	Coordination issues with customer.	Battelle / Customer
Invalid regulatory products that rely on calculations performed with this software.	Low	Development and execution of a Software Test Plan to cover all calculations in the system.	Identify critical calculations and test based on use of the system.	Software codes are required to be reviewed with a customer QA/QC process.	Customer
Overall risk rating is <u>medium</u> .					

18.0 Nonconformances and Deficiencies

Procured materials found to be in nonconformance with specifications or where the quality of an activity is found not to be in compliance, the quality problem will be documented in the ATS in accordance with the SBMS subject area, “[Quality Problem Reporting](#)” (PNNL 2005c). Corrective actions are documented in ATS in accordance with the SBMS subject area, “[Assessment Management](#)” (PNNL 2005a).

If a deficiency is found where a procedure or process is not followed or the activity is not in compliance with a procedure or process, the deficiency will be documented into the ATS in accordance with the SBMS subject area, “[Quality Problem Reporting](#)” (PNNL 2005c). Corrective action will be documented using ATS in accordance with the SBMS subject area, “[Assessment Management](#)” (PNNL 2005a).

Subcontractors will be required to have a system to identify and disposition nonconforming items, procedure deficiencies, processes not followed, or activities not in compliance to a procedure or a process. This requirement will be specified in a SOW.

19.0 Document Control

19.1 Project Quality Assurance Plan Control

Distribution and control of this Quality Assurance Management Plan shall be performed in accordance with SBMS subject area, “[Publishing Scientific and Technical Information](#)” (PNNL 2007d). Modifications to this plan shall be made either by revision or by issuing an Interim Change Notice (ICN). (See Figure 19.1 for the ICN form and instructions.) This plan will be revised after four (4) ICNs or a major change in project scope or requirements. Any PNNL staff member may request a change to this Quality Assurance Management Plan by submitting the requested change in writing to the Project Manager and Quality Engineer. All reviewers listed on the signature page and affected by the change will approve the revision. The ICN will be placed in front of the signature page and the individual pages will be placed or the necessary correction will be lined out and correction added with initial and date. The Quality Assurance Management Plan will be reviewed at least annually unless a different review cycle is documented.

19.2 Technical Procedure Control

Technical procedures referenced by this Quality Assurance Management Plan and used by PNNL staff will be contained in a PNNL internal procedure manual, *Procedures for Ground-Water Investigations* (PNL-MA-567) or other procedure manual, as appropriate. Technical procedures will be distributed and controlled in accordance with SBMS subject area, “[Document Control](#)” (PNNL 2006a). Modifications to any of the internal procedures shall be made either by revision or by issue of an ICN.

INSTRUCTIONS FOR ICN FORM

HEADER:

The ICN number is identified as ICN No.-_____.

For a published document, each page of the ICN shall have a header on the right upper corner that includes the report number, the date and the pagination. The number of the ICN must be placed after the PNNL number. The second line of the header should show the date and pagination. The cover sheet needs to identify how many pages in the ICN packet.

Example header: PNNL-xxxxx-ICN-x
Month, day, year; Page x of xx

SECTION A.

Self-explanatory.

SECTION B.

Include all actions that the document holder must take to update the procedure or instruction. Possible actions include: replacing pages of the document with pages that are distributed with the ICN and marking up the document (in ink) to reflect the changes identified on the ICN or attach the ICN cover sheet to the front of the document.

For a “Published” groundwater monitoring plan include the following statement: “Attach this ICN to the front of the document, just before the title page.”

SECTION C.

Identify, by title, all personnel whose job functions will be affected by the change and include a brief description of the effect. If there is no effect on personnel (e.g., the change was made to clarify the intent of the procedure or to correct a typographical error) this block should be marked “N/A.”

SECTION D.

State the reason for the change followed by a description of the change (including the affected paragraph, information which is deleted, and the actual wording of any replacement text) for each change included on the ICN.

SECTION E.

The Cognizant Manager shall document the reason for not obtaining original reviewers approval and/or any other decisions that must be documented. Additionally, list the individuals who will receive the document (distribution list).

SECTION F.

Identify type of change and document required approvals.

Figure 19.1. Interim Change Notice

INTERIM CHANGE NOTICE (ICN)

A. Document No.: _____ Revision No.: _____ Document Title: _____ Document's Original Author: _____	Implementation Date of ICN: / / <hr/> Change Requested By: _____
B. Action:	
C. Effect of Change:	
D. Reason for Change/Description of Change: Reason for Change: _____ Description of Change: _____	
E. Document Management Decisions:	
F. Task Manager Approval Signatures (Please Sign and Date)	Type of Change (Check one): ___ Minor ___ Major

Project Quality Engineer Approval: _____ **Date:** _____

Author Approval: _____ **Date:** _____

Other Approvals: _____ **Date:** _____

Figure 19.1. (contd.)

Procedures will be revised after two (2) major ICNs, or if the procedure format has changed. Any PNNL staff member may request a change to procedures at any time by submitting the requested change in writing to the author. The author, technical reviewer, groundwater project Task Manager, and project Quality Engineer will review and approve the ICN. The ICN will be placed in front of the signature page and the individual pages will be placed or the necessary correction will be lined out and correction added with initial and date. Contact the Project Quality Engineer for the electronic copy of the ICN. New or revised technical procedures, whether they will be included in the internal procedures manual or not, must be developed in accordance with SBMS subject area, “[Procedures, Permits, and Other Work Instructions](#)” (PNNL 2004). The procedure owner is required to review the procedure at least every two (2) years.

19.3 Administrative Procedure/Instruction Preparation and Control

Administrative procedures/instructions used by PNNL staff will be developed, approved, and controlled to ensure consistent application by those staff performing the defined task(s). These procedures/instructions will be developed, approved, and controlled in a manner that has been approved by appropriate project management and Quality Engineer.

19.4 Groundwater Monitoring Plans

Although the groundwater monitoring scope and a number of PNNL staff have been transferred to FH, PNNL staff may provide input to various monitoring plans and this section is included in the QA Management Plan to be complete. The distribution and control of RCRA groundwater monitoring plans shall be performed in accordance with the SBMS subject area, “[Publishing Scientific and Technical Information](#)” (PNNL 2007e). Different types of monitoring plans have different document change control requirements, as discussed in the following sections. Change control will include internal as well as external (e.g., DOE) requirements.

19.4.1 RCRA Interim-Status Plans

These plans are PNNL documents and are released through ERICA. Modifications to these plans shall be made using an ICN or by revising the plan. (See Figure 19.1 for the ICN form and instructions.) The number of ICNs that may be written for a single plan is not limited so long as revision control is maintained and the working version of the plan and ICN is not in question. Distribution and control of the ICN shall be through ERICA. The author, Groundwater Monitoring Task Manager, and the project Quality Engineer will review and approve the ICN.

Project change control for these plans in the interim period between ICNs or revisions is maintained by the sampling and analysis change request process. These changes are approved by project management, attached to the current plan in project records, and implemented via the project scheduling system.

19.4.2 RCRA Final-Status Plans

Final-status plans may be stand-alone documents that are cited in the Hanford Facility RCRA Permit (Ecology 1994), or contained in the Permit itself. Final-status monitoring plans are revised through the Permit Modification process, which is described in the Tri-Party Agreement (Ecology et al. 1989) and in

the Hanford Facility RCRA Permit (Ecology 1994). Depending on the magnitude (or class) of the changes, they will require contractor and DOE review and approval, regulatory agency review and approval, and/or public review and participation.

19.4.3 CERCLA Sampling and Analysis Plans

Monitoring plans supporting CERCLA groundwater operable units are referred to specifically as sampling and analysis plans (SAPs) and are released as DOE documents. Distribution and control of these plans shall be performed in accordance with the SBMS subject area, “[Publishing Scientific and Technical Information](#)” (PNNL 2007e). The SAPs are reviewed and, if necessary, revised annually; this requires DOE and regulatory agency review and approval. The SAPs may have temporary (duration less than one year) additions (adding constituents, wells, or increasing frequency), or unavoidable changes (such as dry wells, missed or delayed samples); these require notification to project management and DOE, as well as notification to the regulatory agency via email messages or Unit Manager Meeting minutes. Permanent changes (for duration more than one year) are identified to DOE and regulatory agencies for approval prior to documenting them in the revised SAPs. Distribution and control of the revised SAPs shall be by the project editor.

Project change control in the interim period between SAP revisions is maintained by the *Sampling and Analysis Change Request* process. These changes are approved by project management, attached to the current plan in project records, and implemented via the project scheduling system.\

Waste Control Plans and Waste Management Plans also support CERCLA groundwater operable unit activities, and are released as DOE documents. These plans may be revised as needed, based on changes in the activities occurring within the respective operable unit. These plans may have changes made to the well tables (e.g., new wells) that are documented by submitting the revised page(s) to the Unit Manager Meeting minutes. These page revisions are placed with the original plan in the associated operable unit RIDS category of the project records.

19.4.4 Other Monitoring Plans

Other monitoring plans may include plans for *Atomic Energy Act* (AEA) monitoring (e.g., 100-K Basins). These plans are PNNL documents and distribution and control of these plans shall be performed in accordance with SBMS subject area, “[Publishing Scientific and Technical Information](#)” (PNNL 2007e). Modifications to these plans shall be made using an ICN or by revising the plan, as discussed in Section 19.4.1.

Project change control for the plans in the interim period between ICNs or revisions is maintained by the *Sampling and Analysis Change Request* process. These changes are approved by project management, attached to the current plan in project records, and implemented via the project scheduling system.

19.5 Test Plans and Other Work Documents

Test Plans and other work instructions used by PNNL staff will be developed, approved, and controlled to ensure consistent application by those staff performing the defined task(s). These procedures/instructions will be developed, approved, and controlled in a manner that has been approved

by appropriate project management and Quality Engineer. Distribution and control of test plans and other plans shall be performed in accordance with SBMS subject area, “[Publishing Scientific and Technical Information](#)” (PNNL 2007d).

19.6 Field Notebooks and Laboratory Record Books

Field notebooks and laboratory record books (LRBs) used by PNNL staff working on projects contained within the FH Groundwater and Technical Integration Support Projects will be managed, controlled, and reviewed in accordance with the SBMS subject area, “[Laboratory Record Books](#)” (PNNL 2000). In particular: the Project Manager shall ensure that all laboratory record books are reviewed at least twice per year. The reviewer, a qualified individual, confirms that there is sufficient detail to trace the investigation and confirm the test results or repeat the investigation and achieve comparable results, without recourse to the original investigator.

Non- FH Groundwater and Technical Integration Support Project staff, such as subcontractors and/or collaborators shall comply with the following procedural steps regarding laboratory records books, or a Project-approved equivalent:

1. Use laboratory record books with beige-colored binding.
2. The initial laboratory record book custodian shall complete the title, author, and period covered sections of the information block (first sheet inside the cover). If the laboratory record book is transferred, the new custodian shall enter their name, payroll number, location, and date received to the lower portion of the information block.
3. If persons other than the custodian make entries, the custodian shall list above or below the information block on the first sheet inside the cover, the names of those persons and obtain sample signature and initials from each.
4. Use the following procedure as new project number and project or activities are initiated.
 - Record the starting page, the project or activity title in the table of contents.
 - Record as the first entry the research activity title, the project or work authorization number, and a brief description of the objectives and planned approach.
 - Record observations/data chronologically. Describe (narrative or sketch) experimental apparatus, equipment, and any procedures, data sheets, etc., that are used.
5. Date and sign each page. List person(s) who performed the work.
6. Record information only in permanent ink, line out unused portions of pages, and keep pages intact.
7. Do not erase or obliterate entries. Mark out errors or corrections with single lines. Initial and date all changes other than editorial corrections. If the change is substantive, record the reason for it.
8. Use the following steps if it is necessary to attach a loose sheet.
 - a. Attach the sheet to an unused page of the laboratory record book by tape or glue.
 - b. Write the laboratory record book and page numbers on the attached sheet (in case it comes loose).
 - c. Make an entry in the laboratory record book to introduce or describe the attached sheet.

9. Maintain a list in the project or activity file identifying the laboratory record book numbers, custodians, and locations.
10. Record as the last entry for a project or activity a statement noting completion of the work or, if appropriate, reference to a subsequent laboratory record book.
11. Store laboratory record books in metal file cabinets or receptacles that prevent physical damage or access by unauthorized persons when not in use, and allow easy retrieval for periodic inventory.
12. Notify the FH Groundwater and Technical Integration Support Project Document Control in writing when laboratory record books are reassigned.
13. Return laboratory record books to the FH Groundwater and Technical Integration Support Project Document Control when complete or at project end. Users may copy appropriate pages for their personal files and future reference. If the staff member for future reference retains the laboratory record books, they must be protected from physical damage or access by unauthorized persons and made available for periodic inventory.
14. Return laboratory record books to Document Control or request reassignment when the custodian terminates employment.
15. Make copies of laboratory record books, or applicable pages, for inclusion in project files, when appropriate. .

20.0 References

10 CFR 830, Subpart A— “Quality Assurance Requirements.” *U.S. Code of Federal Regulations*.

40 CFR 136, Chapter 1, Appendix B (7/1/01). U.S. Environmental Protection Agency. “Guidelines Establishing Test Procedures for the Analysis of Pollutants.” *U.S. Code of Federal Regulations*.

Atomic Energy Act. 1954, as amended, Ch. 1073, 68 Stat. 919, 42 USC 2011 et seq.

CAWSRP – *Conducting Analytical Work in Support of Regulatory Programs*. 2006. Pacific Northwest National Laboratory. Available online at <http://etd.pnl.gov/docs/conducting-work/index.stm>

CERCLA – *Comprehensive Environmental Response, Compensation, and Liability Act*. 1980. Public Law 96-150, as amended, 94 Stat. 2767, 42 USC 9601 et seq.

DOE Order 414.1C. 2005, as amended. *Quality Assurance*. U.S. Department of Energy, Washington, D.C.

DOE Order 435.1. 2001, as amended. *Radioactive Waste Management*. U.S. Department of Energy, Washington, D.C.

DOE Order 450.1. 2003, as amended. *Environmental Management System*. U.S. Department of Energy, Washington, D.C.

DOE Order 5400.5. 1993, as amended. *Radiation Protection of the Public and the Environment*. U.S. Department of Energy, Washington, D.C.

DOE/RL-96-68. 1998. *Hanford Analytical Services Quality Assurance Requirements Documents*. HASQARD, Volumes 1, 2, 3, and 4. U.S. Department of Energy, Richland Operations Office, Richland, Washington.

Ecology - Washington State Department of Ecology, U.S. Environmental Protection Agency, and U.S. Department of Energy. 1989, as amended. *Hanford Federal Facility Agreement and Consent Order*. Document No. 89-10 (Tri-Party Agreement), Olympia, Washington.

Ecology. 1994. *Dangerous Waste Portion of the Resource Conservation and Recovery Act Permit for the Treatment, Storage, and Disposal of Dangerous Waste*. Permit Number WA7890008967, as amended. Washington State Department of Ecology, Olympia, Washington.

EMSL-LV-0539-17. 1979. *Radiochemical Analytical Procedures for Analysis of Environmental Samples*. U.S. Environmental Protection Agency, Las Vegas, Nevada.

EPA/240/B-01/003. 2001. *EPA Requirements for Quality Assurance Project Plans (QA/R-5)*. U.S. Environmental Protection Agency, Washington, D.C.

EPA/240/B-06/001. 2006. *Guidance on Systematic Planning Using the Data Quality Objectives Process (QA/G-4)*. U.S. Environmental Protection Agency, Washington, D.C.

EPA-600/4-79/019. 1979. *Handbook for Analytical Quality Control in Water and Wastewater Laboratories*. U.S. Environmental Protection Agency, Cincinnati, Ohio.

EPA-600/4-79-020. 1983. *Methods for Chemical Analysis of Water and Wastes*. U.S. Environmental Protection Agency, Washington, D.C.

EPA-600/4-80-032. 1980. *Prescribed Procedures for Measurement of Radioactivity in Drinking Water*. U.S. Environmental Protection Agency, Cincinnati, Ohio.

EPA-600/4-88-039. 1988. *Methods for the Determination of Organic Compounds in Drinking Water*. U.S. Environmental Protection Agency, Washington, D.C.

EPA/600/R-96/055. 2000. *Guidance for the Data Quality Objectives Process (QA/G-4)*, U.S. Environmental Protection Agency, Washington, D.C.

EPA-R4-73-014. 1973. *Procedures for Radiochemical Analysis of Nuclear Reactor Aqueous Solutions*. U.S. Environmental Protection Agency, Cincinnati, Ohio.

EPA/SW-846. 1986, as amended. *Test Methods for Evaluating Solid Waste: Physical/Chemical Methods*, SW-846, Third Edition. Office of Solid Waste and Emergency Response, U.S. Environmental Protection Agency, Washington, D.C. Available online at <http://www.epa.gov/epaoswer/hazwaste/test/main.htm>

ESL QAP. *Environmental Sciences Laboratory QA Plan*, current revision. Pacific Northwest National Laboratory, Richland, Washington.

National Water Well Association. 1986. *RCRA Ground Water Monitoring Technical Enforcement Guidance Document*. Dublin, Ohio.

NQA-1-2000. 2001. *Quality Assurance Requirements for Nuclear Facility Applications*. The American Society of Mechanical Engineers, New York, New York.

PAAA-Price-Anderson Amendments Act. *Energy Policy Act of 2005*. Title VI—Nuclear Matters, Subtitle A—Price-Anderson Act Amendments, Section 601 et. seq. Public Law 109-58, as amended. 42 USC 15801 et seq.

PNL-MA-567. 1993, as amended. *Procedures for Ground-Water Investigations*. Pacific Northwest National Laboratory, Richland, Washington.

PNL-MA-580. 2004, as amended. *Surface Environmental Surveillance Procedures Manual*, Revision 4. Pacific Northwest National Laboratory, Richland, Washington.

PNNL. 2000. *Laboratory Record Books*. Standards-Based Management System, Pacific Northwest National Laboratory, Richland, Washington. Available online at <http://sbms.pnl.gov/standard/2l/2l00t010.htm>

PNNL. 2002a. *Training Design, Development, Implementation and Evaluation*. Standards-Based Management System, Pacific Northwest National Laboratory, Richland, Washington. Available online at <http://sbms.pnl.gov/standard/1f/1f00t010.htm>

PNNL. 2004. *Procedures, Permits, and Other Work Instructions*. Standards-Based Management System, Pacific Northwest National Laboratory, Richland, Washington. Available online at <http://sbms.pnl.gov/standard/74/7400t010.htm>

PNNL. 2005a. *Assessment Management*. Standards-Based Management System, Pacific Northwest National Laboratory, Richland, Washington. Available online at <http://sbms.pnl.gov/standard/4i/4i00t010.htm>

PNNL. 2005b. *Calibration*. Standards-Based Management System, Pacific Northwest National Laboratory, Richland, Washington. Available online at <http://sbms.pnl.gov/standard/79/7900t010.htm>

PNNL. 2005c. *Quality Problems Reporting*. Standards-Based Management System, Pacific Northwest National Laboratory, Richland, Washington. Available online at <http://sbms.pnl.gov/standard/78/7800t010.htm>

PNNL. 2005d. *Training and Qualification for Staff and Non-Staff*. Standards-Based Management System, Pacific Northwest National Laboratory, Richland, Washington. Available online at <http://sbms.pnl.gov/standard/1e/1e00t010.htm>

PNNL. 2006a. *Document Control*. Standards-Based Management System, Pacific Northwest National Laboratory, Richland, Washington. Available online at <http://sbms.pnl.gov/standard/2m/2m00t010.htm>

PNNL. 2006b. *Policies and Standards*. Standards-Based Management System, Pacific Northwest National Laboratory, Richland, Washington. Available online at <http://sbms.pnl.gov/private/policies/bp00t010.htm>

PNNL 2007a. *Hazardous Materials, Packaging and Shipping*. Standards-Based Management System, Pacific Northwest National Laboratory, Richland, Washington. Available online at <http://sbms.pnl.gov/standard/66/6600t010.htm>

PNNL. 2007b. *Planning, Assessment, and Analysis*. Standards-Based Management System, Pacific Northwest National Laboratory, Richland, Washington. Available online at <http://sbms.pnl.gov/standard/18/1800t010.htm>

PNNL. 2007c. *Price-Anderson Amendments Act*. Standards-Based Management System, Pacific Northwest National Laboratory, Richland, Washington. Available online at <http://sbms.pnl.gov/standard/11/1100t010.htm>

PNNL. 2007d. *Publishing Scientific and Technical Information*. Standards-Based Management System, Pacific Northwest National Laboratory, Richland, Washington. Available online at <http://sbms.pnl.gov/standard/80/8000t010.htm>

PNNL. 2007e. *Purchasing Goods and Services*. Standards-Based Management System, Pacific Northwest National Laboratory, Richland, Washington. Available online at <http://sbms.pnl.gov/standard/3i/3i00t010.htm>

PNNL. 2007f. *Records Management*. Standards-Based Management System, Pacific Northwest National Laboratory, Richland, Washington. Available online at <http://sbms.pnl.gov/standard/1a/1a00t010.htm>

PNNL. 2007g. *Safety Software*. Standards-Based Management System, Pacific Northwest National Laboratory, Richland, Washington. Available online at <http://sbms.pnl.gov/standard/6e/6e00t010.htm>

PNNL. 2007h. *Sample Handling, Archival, and Disposal*. Standards-Based Management System, Pacific Northwest National Laboratory, Richland, Washington. Available online at <http://sbms.pnl.gov/standard/2h/2h00t010.htm>

PNNL. 2007i. *Software*. Standards-Based Management System, Pacific Northwest National Laboratory, Richland, Washington. Available online at <http://sbms.pnl.gov/standard/94/9400t010.htm>

PNNL. 2007j. *Waste, Managing*. Standards-Based Management System, Pacific Northwest National Laboratory, Richland, Washington. Available online at <http://sbms.pnl.gov/standard/0f/0f00t010.htm>

RCRA – *Resource Conservation and Recovery Act*. 1976. Public Law 94-580, as amended, 90 Stat. 2795, 42 USC 6901 et seq.

U.S. Geological Survey. 1977. *National Handbook of Recommended Methods for Water Data Acquisition*. Office of Water Data Coordination. Reston, Virginia.

WAC 173-160. “Minimum Standards for Construction and Maintenance of Wells.” *Washington Administrative Code*, Olympia, Washington.

Appendix A

The Fluor Hanford, Inc. Groundwater and Technical Integration Support (Master Project) Quality Control Plan

Appendix A

The Fluor Hanford, Inc. Groundwater and Technical Integration Support (Master Project) Quality Control Plan

A.1 Introduction

This appendix describes the basic methods and procedures to implement a groundwater monitoring quality control task for sampling and analysis conducted in association with the Fluor Hanford, Inc. Groundwater and Technical Integration Support Project. Although the groundwater monitoring scope has been transferred to FH, PNNL staff may provide input to various monitoring plans and this appendix is included in the QAP to be complete. The quality control (QC) practices described in this plan help to evaluate whether samples free of contamination are obtained during sampling and that the laboratory performed sample analyses within the accuracy and precision limits required by the project.

Most of the information in this appendix applies only to groundwater samples. Quality control practices and requirements that pertain to soil and sediment samples are described in section A.5.

The primary objectives of this plan are listed below:

1. Identify the QC elements selected for the Groundwater Performance Assessment Project
2. Provide data quality objectives (DQO) for reporting limits, precision, accuracy, and completeness
3. Indicate actions that are to be taken for out of tolerance data.

Data quality needs for certain *Resource Conservation and Recovery Act* (RCRA) facilities may be more stringent than the QC criteria defined in this plan. DQOs for those units are defined in the groundwater monitoring plans specific to those sites.

A.2 Technical Requirements

The technical requirements for QC are divided into two (2) types – components that provide checks on field and laboratory activities (Field QC) and factors that help to monitor laboratory performance (Laboratory QC). Each type of QC sample has required frequencies and acceptance criteria.

The following guidance documents were used as aids in determining the QC elements necessary for the Groundwater Performance Assessment Project:

1. *Quality Assurance Manual for the Waste Management Branch Investigations* (EPA 910/9-86-00)
2. *Resource Conservation and Recovery Act (RCRA) Groundwater Monitoring Technical Enforcement Guidance Document* (EPA/OSWER-9950.1)
3. *Test Methods for Evaluating Solid Waste: Physical/Chemical Methods, SW-846, Third Edition* (EPA/SW-846)
4. *Handbook for Analytical Quality Control in Water and Wastewater Laboratories* (EPA-600/4-79-019).

5. *Hanford Analytical Services Quality Assurance Requirements Documents (HASQARD)* (DOE/RL-96-68).

QC elements were selected based on the needs of the project and value that results from each type of sample will add to the database.

A.2.1 Field Quality Control

To indicate whether groundwater samples are collected in a consistent manner and are properly preserved and transported to the analytical laboratory, four types of QC samples are collected before or during sampling:

1. **Full Trip Blanks (FTB)** — These samples are prepared by the sampling team before traveling to a sampling site. A preserved bottle set, identical to the set that will be used for sample collection in the field, is filled with reagent water (carbon free, deionized water). Dead water from well 699-S11-E12AP is used for low-level tritium FTBs. The FTB bottles are sealed by the sampling team and transported unopened to the field in the same storage container that will be used for the samples collected that day. These samples are typically analyzed for the same constituents as the samples from the associated well.
2. **Field Transfer Blanks (FXR)** — Preserved volatile organic analysis (VOA) sample bottles are filled at the sample collection site with reagent water that has been transported to the field. The samples are prepared during the sampling of a well to evaluate potential contamination caused by conditions in the field. After collection, the FXR bottles are sealed and placed in the same sample storage container as the rest of the samples. The FXR bottles are not removed from the storage container until delivery to the analytical laboratory. FXR samples are typically analyzed for volatile organic compounds (VOC) only.
3. **Equipment Blanks (EB)** — Reagent water is passed through the pump or manifold after decontamination (sometimes just prior to sampling) to collect blank samples identical to a set that will be collected in the field. Preserved bottles are used. The EB bottles are placed in the same container as the associated field samples. EB samples are not removed from the container until delivery to the analytical laboratory.
4. **Field Duplicates (DUP)** — A replicate sample that is collected at one well. After each type of bottle is filled, a second, identical bottle is filled for each type of analysis as directed by chain-of-custody requirements. Both sets of samples are stored and transported together.

Using several types of field blank samples provides checks on bottle cleanliness, preservative purity, equipment decontamination, proper storage and transport of samples, and reveals whether or not samples collected for volatiles may have been contaminated during collection. Sampling in replicate provides information about sampling reproducibility. Field QC sample frequencies are shown in Table A.1. In addition to the evaluation characteristics described in Table A.1, the field QC samples also provide a check on the analytical laboratory. The field QC data are designed to give an overall impression of the performance of the sampling and analysis of the FH Groundwater and Technical Support Project; however, individual data points associated with field QC samples that are outside of the acceptance criteria are flagged in the HEIS database.

Table A.1. Quality Control Samples

Field QC		
Sample Type	Primary Characteristics Evaluated	Frequency
Sample Event Blank	Contamination from containers or transportation	1 per 20 wells sampled
Equipment Blank	Contamination from non-dedicated equipment	As needed(a)
Replicate/Duplicate Samples	Reproducibility	1 per 20 wells sampled
Laboratory QC		
Sample Type	Primary Characteristics Evaluated	Frequency
Method Blanks	Laboratory Contamination	1 per batch
Lab Duplicates	Laboratory Reproducibility	(b)
Matrix Spikes	Matrix Effect and Laboratory Accuracy	(b)
Matrix Spike Duplicates	Laboratory Reproducibility/Accuracy	(b)
Surrogates	Recovery/Yield	(b)
Laboratory Control Samples	Method Accuracy	1 per batch
(a) For portable Grundfos pumps, equipment blanks are collected one per ten well trips. Whenever a new type of non-dedicated equipment is used, an equipment blank shall be collected every time sampling occurs until it can be shown that less frequent collection of equipment blanks is adequate to monitor the decontamination procedure for the non-dedicated equipment. (b) As defined in the laboratory contract or QA plan and/or analysis procedures. QA = Quality assurance. QC = Quality control.		

The results of each type of field QC sample are evaluated according to criteria defined in Table A.2.

Table A.2. Field and Laboratory QC Elements and Acceptance Criteria

Method	QC Element	Acceptance criteria	Corrective action
General Chemical Parameters			
Alkalinity - EPA 600 Series, 310.1	MB(a)	< MDL	Flagged with "C"
Chemical Oxygen Demand - EPA 600 Series, 410.4	LCS	80-120% recovery(b)	Data reviewed(c)
Conductivity - EPA 600 Series, 120.1	DUP	± 20% RPD(b)	Data reviewed(c)
Oil and Grease - EPA 600 Series, 413.1	MS(d)	75-125% recovery(b)	Flagged with "N"
pH - EPA 600 Series, 150.1	EB, FTB	< 2X MDL	Flagged with "Q"
Total Dissolved Solids - EPA 600 Series, 160.1	Field Duplicate	± 20% RPD(e)	Flagged with "Q"
Total Organic Carbon - SW-846, 9060			
Total Organic Halides - SW-846, 9020			
Ammonia and Anions			
Ammonia - EPA 600 Series, 350.1	MB	< MDL	Flagged with "C"
Anions by IC - EPA 600 Series, 300.0	LCS	80-120% recovery(b)	Data reviewed(c)
Cyanide - SW-846, 9012	DUP	± 20% RPD(b)	Data reviewed(c)
	MS	75-125% recovery(b)	Flagged with "N"
	EB, FTB	< 2X MDL	Flagged with "Q"
	Field Duplicate	± 20% RPD(e)	Flagged with "Q"

Table A.2. (contd)

Method	QC Element	Acceptance Criteria	Corrective Action
Metals			
Arsenic - SW-846, 7060	MB	< CRDL	Flagged with "C"
Cadmium - SW-846, 7131	LCS	80-120% recovery(b)	Data reviewed(c)
Chromium - SW-846, 7191	MS	75-125% recovery(b)	Flagged with "N"
Lead - SW-846, 7421	MSD	± 20% RPD(b)	Data reviewed(c)
Mercury - SW-846, 7470	EB, FTB	< 2X MDL	Flagged with "Q"
Selenium - SW-846, 7740	Field Duplicate	± 20% RPD(e)	Flagged with "Q"
Thallium - SW-846, 7841			
ICP Metals - SW-846, 6010			
ICP/MS Metals - SW-846, 6020			
Radiological Parameters			
Gamma Scan	MB	< 2X MDA	Flagged with "B"
Gross Alpha - SW-846, 9310	LCS	70-130% recovery	Data reviewed(c)
Gross Beta - SW-846, 9310	DUP	± 20% RPD	Data reviewed(c)
Iodine-129	MS(h)	60-140% recovery	Flagged with "N"
Plutonium (isotopic)	EB, FTB	< 2X MDA	Flagged with "Q"
Strontium-89/90	Field Duplicate	± 20% RPD(5)	Flagged with "Q"
Technetium-99			
Tritium - SW-846, 906.0			
Tritium (low-level)			
Uranium (isotopic)			
Uranium (total)			
<p>(a) Does not apply to pH.</p> <p>(b) Laboratory-determined, statistically derived control limits may also be used. Such limits are reported with the data.</p> <p>(c) After review, corrective actions are determined on a case-by-case basis. Corrective actions may include a laboratory recheck or flagging the data as suspect (Y flag) or rejected (R flag).</p> <p>(d) Applies to total organic carbon and total organic halides only.</p> <p>(e) Applies only in cases where one or both results are greater than 5X the detection limit.</p> <p>(f) Determined by the laboratory based on historical data. Control limits are reported with the data.</p> <p>(g) For common laboratory contaminants such as acetone, methylene chloride, 2-butanone, toluene, and phthalate esters, the acceptance criteria is < 5X MDL.</p> <p>(h) Applies only to technetium-99 and total uranium analyses.</p> <p>Data Flags:</p> <p>B, C = Possible laboratory contamination (analyte was detected in the associated method blank).</p> <p>N = result may be biased (associated matrix spike result was outside the acceptance limits).</p> <p>Q = problem with associated field QC sample (blank and/or duplicate results were out of limits).</p> <p>DUP = Laboratory matrix duplicate.</p> <p>EB = Equipment blank.</p> <p>FTB = Full trip blank.</p> <p>FXR = Field transfer blank.</p> <p>GC = Gas chromatography.</p> <p>ICP = Inductively coupled plasma.</p> <p>ICP/MS = Inductively coupled plasma-mass spectrometry.</p> <p>LCS = Laboratory control sample.</p> <p>MB = Method blank.</p> <p>MDA = Minimum detectable activity.</p> <p>MDL = Method detection limit.</p> <p>MS = Matrix spike.</p> <p>MSD = Matrix spike duplicate.</p> <p>PCBs = Polychlorinated biphenyls.</p> <p>RPD = Relative percent difference.</p> <p>SUR = Surrogate.</p>			

Bias will be assessed by comparing a measured value to a known or accepted reference value or the recovery of a known amount of spiked contaminant into a sample (i.e., a matrix spike). For a matrix spike (MS) bias caused by matrix effects will be calculated as follows in Equation (A.1):

$$B = (X_s - X_u) - K \quad A.1$$

Where

X_s = measured value of spiked sample
 X_u = sample or miscellaneous contribution
 K = known value of spike

Using Equation (A.2) yields percent recovery (%R):

$$\%R = 100 (X_s - X_u) / K \quad A.2$$

Analytical precision will be determined by analyzing duplicates (field or lab). Precision is expressed as either percent relative standard deviation (RSD) or relative percent difference (RPD). Duplicate results will be flagged if the results of both samples are quantifiable (i.e., the result is greater than the 5 times the instrument detection limit [IDL]/method detection limit [MDL]/minimum detectable activity [MDA]) and the RPD is greater than 20%. The RPD is calculated as follows in Equation (A.3):

$$RPD = \frac{D_1 - D_2}{(D_1 + D_2) / 2} \times 100 \quad A.3$$

Where

D_1 = original sample value
 D_2 = duplicate sample value

When more than two data values are present, precision is calculated by the RSD as shown in Equation (A.4):

$$RSD = \frac{\text{standard deviation}}{\text{mean}} \times 100 \quad A.4$$

A.2.2 Quality Control in the Laboratory

The ability of the laboratories to perform sample analyses within the limits established by the project is monitored in several ways. Internal quality assurance programs are maintained by laboratories utilized by the Groundwater Performance Assessment Project. In addition, the laboratories are periodically reviewed and audited both internally and externally. PNNL participates in external audits. Laboratory quality assurance includes a comprehensive quality control program, which includes the use of matrix spikes (MS), matrix duplicates (MD), matrix spike duplicates (MSD), laboratory control samples (LCS), surrogates, tracers, and blanks. These samples are recommended in the guidance documents and are required by U.S. Environmental Protection Agency (EPA) protocol.

Matrix Duplicate (MD) — An intra-laboratory split sample that is used to evaluate the precision of a method in a given sample matrix.

Matrix Spike (MS) — An aliquot of a sample spiked with a known concentration of target analyte(s). The MS is used to assess the bias of a method in a given sample matrix. Spiking occurs prior to sample preparation and analysis.

Matrix Spike Duplicate (MSD) — A replicate spiked aliquot of a sample that is subjected to the entire sample preparation and analytical process. MSD results are used to determine the bias and precision of a method in a given sample matrix.

Laboratory Control Sample (LCS) — A control matrix spike (e.g., deionized water) spiked with analytes representative of the target analytes or a certified reference material that is used to evaluate laboratory accuracy.

Method Blank — An analyte-free matrix to which all reagents are added in the same volumes or proportions as used in sample processing. The method blank is carried through the complete sample preparations and analytical procedure. The method blank is used to quantify contamination resulting from the analytical process.

Surrogates — A compound added to all samples in the analysis batch (field samples and QC samples) prior to preparation. The surrogate is typically similar in chemical composition to the compound or analyte being determined, yet not normally encountered in most samples. Surrogates are expected to respond to the preparation and measurement systems in a manner similar to the analytes of interest. Because surrogates are added to all standards, samples, and QC samples, they are a useful tool in evaluating overall method performance in a given matrix. Surrogates are utilized only in organic analyses.

Tracers — A tracer is a known quantity of radioactive isotope that is different from that of the isotope of interest but is expected to behave similarly and is added to an aliquot of sample. Sample results are generally corrected based on tracer recovery.

The laboratories are required to analyze samples within the holding times specified by the analysis procedure. In some instances, constituents in samples not analyzed within the holding time may be compromised by volatilization, decomposition or other chemical changes. Data from samples analyzed outside the holding time are flagged in the HEIS database with an H. The holding times for constituents frequently analyzed by the Groundwater Performance Assessment Project are listed in Table A.3.

Other tools are used by the project to evaluate the laboratories. Double-blind standards of the constituents of concern are submitted to the primary laboratory in triplicate or quadruplicate on a quarterly basis. Because the results of double-blind standards provide information on laboratory precision and accuracy, these standards are useful tools to verify that the project DQOs is being met. Table A.4 lists the typical blind-standard constituents and their submission frequencies. Due to the occasional need to investigate potential problems at the laboratories, the list of constituents is subject to change. Specific information about the constituents used and their spiking levels will be maintained in the project files.

Blind standards are prepared by spiking matrix groundwater and deionized water with known concentrations of constituents of interest. Spiking concentrations range from MDA or MDL, depending on the constituent measured, to the upper limit of concentration determined in groundwater on the Hanford Site. The matrix groundwater wells chosen are 699-49-100C for radiochemical analytes, and

total organic halides (TOX); and 699-19-88 for cyanide, anions, inductively coupled plasma (ICP) metals, and total organic carbon (TOC). Deionized water is used to prepare VOCs. Well 699-49-100C is located to the west of the Hanford Site. Well 699-19-88 is a southern boundary well. Both wells are considered free of the contaminant migration zone. Dead water from well 699-S11-E12AP is used to prepare low-level tritium blind standards.

Table A.3. Sample Holding Times

Constituents	Methods	Holding Times
Volatile organics	SW-846, ^(a) 8010/8020/8260	14 days
Semivolatile organics	SW-846, 8270	7 days before extraction 40 days after extraction
Pesticides	SW-846, 8080	7 days before extraction 40 days after extraction
Polychlorinated biphenyls	SW-846, 8080	7 days before extraction 40 days after extraction
Chlorinated herbicides	SW-846, 8150	7 days before extraction 40 days after extraction
Phenols	SW-846, 8040	7 days before extraction 40 days after extraction
ICP metals	SW-846, 6010	6 months
ICP-MS	SW-846, 6020	6 months
Arsenic	SW-846, 7060	6 months
Lead	SW-846, 7421	6 months
Mercury	SW-846, 7470/7471	28 days
Selenium	SW-846, 7740	6 months
Thallium	SW-846, 7841	6 months
Alkalinity	EPA 600 Series, 310.1	14 days
Cyanide	SW-846, 9010/9012	14 days
Bromide	EPA 600 Series, 300.0	28 days
Chloride	EPA 600 Series, 300.0	28 days
Fluoride	EPA 600 Series, 300.0	28 days
Nitrate	EPA 600 Series, 300.0	48 hours
Nitrite	EPA 600 Series, 300.0	48 hours
Phosphate	EPA 600 Series, 300.0	48 hours
Sulfate	EPA 600 Series, 300.0	28 days
Total organic carbon	SW-846, 9060	28 days
Total organic halides	SW-846, 9020	28 days
Chemical oxygen demand	EPA 600 Series, 410.4	28 days
(a) EPA/SW-846, as amended.		

Blind-standard results are evaluated by comparing the laboratory results to the actual spike values. Laboratory precision also is considered as the samples are sent to the laboratory in replicate. Laboratory results are evaluated based on the recovery and precision criteria listed in Table A.4. Results outside of these control limits are investigated and appropriate actions are taken, if necessary.

Table A.4. Blind-Standard Constituents and Schedule

Constituents	Frequency	Recommended Recovery (%) ^(a)	Precision (%RSD) ^(a)
Carbon tetrachloride	Quarterly	±25 %	±25 %
Chloroform	Quarterly	±25 %	±25 %
Trichloroethylene	Quarterly	±25 %	±25 %
Fluoride	Quarterly	±25 %	±25 %
Nitrate	Quarterly	±25 %	±25 %
Cyanide	Quarterly	±25 %	±25 %
Chromium	Annually	±20 %	±20 %
Total organic carbon ^(b)	Quarterly	Varies according to spiking compound	Varies according to spiking compound
Total organic halides ^(c)	Quarterly	Varies according to spiking compound	Varies according to spiking compound
Gross alpha ^(d)	Quarterly	70 - 130 %	±20 %
Gross beta ^(e)	Quarterly	70 - 130 %	±20 %
Tritium	Annually	70 - 130 %	±20 %
Tritium (low level)	Semi-annual	70 - 130 %	±20 %
Cobalt-60	Annually	70 - 130 %	±20 %
Strontium-90	Quarterly	70 - 130 %	±20 %
Techneium-99	Quarterly	70 - 130 %	±20 %
Iodine-129	Semi-annually	70 - 130 %	±20 %
Cesium-137	Annually	70 - 130 %	±20 %
Uranium	Quarterly	70 - 130 %	±20 %
Plutonium-239/240	Quarterly	70 - 130 %	±20 %
<p>(a) If the results are less than five times the required detection limit, the criteria is that the difference of the results of the replicates is less than the required detection limit.</p> <p>(b) The spiking compound generally used for total organic carbon (TOC) is potassium phthalate. Other spiking compounds may also be used.</p> <p>(c) Two sets of spikes for total organic halides (TOX) will be used. The spiking compound for one set should be 2,4,5-trichlorophenol. The spiking compound for the second set should include the constituents used for the volatile organic compounds (VOC) sample (carbon tetrachloride, chloroform, trichloroethylene).</p> <p>(d) The gross alpha sample will be prepared from Pu-239.</p> <p>(e) The gross beta sample will be prepared from Sr-90.</p> <p>RSD = Relative standard deviation.</p>			

The laboratories also participate in the nationally based studies conducted by Environmental Resources Associates, New York State Department of Health, and DOE to evaluate laboratory performance for chemical and radiological constituents. Reports from these performance evaluation studies are reviewed quarterly by the QC sub-task manager. These reports provide an independent check on laboratory performance. If a laboratory has results that are outside of the acceptance range for one of these studies, the laboratory proposed corrective actions are requested and evaluated. The QC sub-task manager will respond to the corrective actions as appropriate.

A.3 Data Quality Objectives

DQOs are defined for reporting limits, precision, accuracy, and completeness. Groundwater monitoring plans or sampling analysis plans specify whether or not a particular site has more stringent DQOs than those specified in this plan.

Limits for precision and accuracy for chemical analyses are based on criteria stipulated in the methods (e.g., EPA/SW-846, EPA 600 series). Precision and accuracy limits for radiochemical results are specified in the laboratory contract.

Completeness is defined as the percentage of data points judged to be valid. The percent complete each quarter should be at least 85%.

Reporting limits for radiochemical constituents are defined in the laboratory contract. Reporting limits as low as one third the derived 4-mrem-dose requirement are preferred, but not always achievable. Preferred reporting limits and actual reporting limits are listed in Table A.5 for radiochemical constituents. For chemical constituents, MDLs as low as one third the EPA drinking water standards are preferred. In some cases, MDLs that are one third the regulatory limit are not feasible (e.g., pentachlorophenol and cadmium). Because MDLs change frequently, these values are not provided in this document.

Table A.5. Reporting Limits for Radiochemical Constituents

Constituent of Concern	Method	CAS #	DWS	1/3 DWS	RDL
Gross Alpha	Gross Alpha - GA	12587-46-1	15 pCi/L*	5 pCi/L*	3 pCi/L
Gross Beta	Gross Beta - GB	12587-47-2	N/A	N/A	4 pCi/L
Cobalt-60	Gamma Spec	10198-40-0	100 pCi/L	33 pCi/L	25 pCi/L
Cesium-137	--	10045-97-3	200 pCi/L	67 pCi/L	15 pCi/L
Europium-152	--	--	--	--	50 pCi/L
Europium-154	--	--	200 pCi/L	67 pCi/L	50 pCi/L
Europium-155	--	--	600 pCi/L	200 pCi/L	50 pCi/L
Tritium	H-3	10028-17-8	20,000 pCi/L	6700 pCi/L	400 pCi/L
Tritium	H-3 (LL)	N/A	N/A	N/A	10 pCi/L
Iodine-129	I-129	10043-66-0	1 pCi/L	0.33 pCi/L	5 pCi/L
Iodine-129	I-129 (LL)	N/A	N/A	N/A	1 pCi/L
Strontium-90	Sr-89/Sr-90	10098-97-2	8 pCi/L	2.7 pCi/L	2 pCi/L
Technetium-99	Tc-99	14133-76-7	900 pCi/L	300 pCi/L	15 pCi/L
Plutonium-238	Isotopic Plutonium		1.6 pCi/L	0.5 pCi/L	1 pCi/L
Plutonium-239/240	Pu-AEA		1.2 pCi/L	0.4 pCi/L	1 pCi/L
Uranium-233	Isotopic Uranium	13968-55-3	20 pCi/L	6.7 pCi/L	1 pCi/L
Uranium-234	Isotopic Uranium	13966-29-5	20 pCi/L	6.7 pCi/L	1 pCi/L
Uranium-235	Uranium-AEA	15117-96-1	24 pCi/L	8 pCi/L	1 pCi/L
Uranium-238		U-238	24 pCi/L	8 pCi/L	1 pCi/L
Total Alpha Energy Emitted from Radium	Total Radium	N/A	N/A	N/A	1 pCi/L

Constituent of Concern	Method	CAS #	DWS	1/3 DWS	RDL
Uranium (elemental)	Total Uranium	N/A	30 µg/L	10 µg/L	0.1 µg/L
* Excluding uranium CAS# = Chemical abstract service number. DWS = Drinking water standard. N/A = Not applicable. RDL = Required detection limit.					

A.4 Reporting and Deliverables Requirements

The results of the blind standards and the field QC samples will be provided through current analytical reporting procedures.

A.5 Project Records

All project records associated with quality control are maintained in accordance with established RIDS for the relevant projects providing sample analysis and reporting.

A.6 Requirements for Soil and Sediment Samples

Occasionally, projects may analyze soil or sediment samples in support of site-characterization activities. The types, quantities, and acceptance criteria for field and/or laboratory QC samples are specified in monitoring plans and/or the laboratory statement of work. Table A.6 lists the maximum recommended holding times for common analytes in soils. Radionuclides are not included in the table.

Table A.6. Holding Times for Soil and Sediment Analyses

Constituents	Methods	Holding Times
Volatile organics	SW-846, ^(a) 8260	14 days
Semivolatile organics	SW-846, 8270	14 days before extraction 40 days after extraction
Pesticides	SW-846, 8080	14 days before extraction 40 days after extraction
Polychlorinated biphenyls	SW-846, 8080	14 days before extraction 40 days after extraction
Chlorinated herbicides	SW-846, 8150	14 days before extraction 40 days after extraction
Phenols	SW-846, 8040	14 days before extraction 40 days after extraction
ICP metals	SW-846, 6010	6 months
ICP-MS	SW-846, 6020	6 months
Arsenic	SW-846, 7060	6 months
Lead	SW-846, 7421	6 months
Mercury	SW-846, 7470/7471	28 days
Selenium	SW-846, 7740	6 months
Thallium	SW-846, 7841	6 months
Alkalinity	EPA 600 Series, 310.1	14 days
Cyanide	SW-846, 9010/9012	14 days

Constituents	Methods	Holding Times
Bromide	EPA 600 Series, 300.0	28 days
Chloride	EPA 600 Series, 300.0	28 days
Fluoride	EPA 600 Series, 300.0	28 days
Nitrate	EPA 600 Series, 300.0	48 hours
Nitrite	EPA 600 Series, 300.0	48 hours
Phosphate	EPA 600 Series, 300.0	48 hours
Sulfate	EPA 600 Series, 300.0	28 days
Total organic carbon	SW-846, 9060	28 days
Total organic halides	SW-846, 9020	28 days
Chemical oxygen demand	EPA 600 Series, 410.4	28 days
(a) EPA/SW-846, as amended.		

A.7 References

DOE/RL-96-68. 1998. *Hanford Analytical Services Quality Assurance Requirements Documents*. (HASQARD), Volumes 1 through 4, U.S. Department of Energy, Richland, Washington.

DOH. 1990. *Washington State Environmental Radiation Program Annual Report*. Washington State Department of Health, Olympia, Washington.

EPA-600/4-79-019. 1979. *Handbook for Analytical Quality Control in Water and Wastewater Laboratories*. U.S. Environmental Protection Agency, Cincinnati, Ohio.

EPA 910/9-86-00. 1986. *Quality Assurance Manual for Waste Management Branch Investigations*. U.S. Environmental Protection Agency, Region 10, Seattle, Washington.

EPA/OWSER-9950.1. 1986. *Resource Conservation and Recovery Act (RCRA) Groundwater Monitoring Technical Enforcement Guidance Document*. U.S. Environmental Protection Agency, Washington, D.C.

EPA/SW-846. 1986, as amended. *Test Methods for Evaluating Solid Waste: Physical/Chemical Methods, SW-846, Third Edition*. Office of Solid Waste and Emergency Response, U.S. Environmental Protection Agency, Washington, D.C. Available online at <http://www.epa.gov/epaoswer/hazwaste/test/sw846.htm>.

PNNL-145670. 2006. *Hanford Site Groundwater Monitoring for Fiscal Year 2005*. MJ Hartman, LF Morasch, and WD Webber (eds.), Pacific Northwest National Laboratory, Richland, Washington.

Appendix B

Experimental and Modeling Procedures for the Subsurface Science Representative Sites Task

Appendix B

Experimental and Modeling Procedures for the Subsurface Science Representative Sites Task

Method	Analysis	Document Number	Procedure Title
Conduct of Routine Laboratory Operations	General	RPL-OP-001	Routine Research Operations Section 31 tab 3 of <i>RPL Laboratory Handbook</i>
Inductively Coupled Plasma-Optical Emission Spectroscopy (ICP-OES)*	Ca, K, Mg, P, Sr, Na, Si, Cu, Fe, Mn, S, and Ti in water in ppb or moles/L	PNNL-AGG-ICP-AES*	Inductively Couple Plasma – Optical Emission Spectrometry (ICP-OES) Analysis
Inductively Coupled Plasma-Mass Spectroscopy (ICP-MS)	Re, Tc	PNNL-AGG-415	Inductively Coupled Plasma Mass Spectrometric (ICP-MS) Analysis
Ion Chromatography	F, Cl, NO ₂ , NO ₃ , CO ₃ , SO ₄ , PO ₄ , PO ₄ in water in ppm or moles/L	*PNNL-AGG-IC-001	Determinations by Ion Chromatography (IC)
ICP/MS	Cu, Fe in water in ppb or moles/L	PNL-SAND-3.1 (needs to be updated)	--
KPA	U in water in ppb or moles/L	Liu et al. (2004)	--
Spectrophotometer	Fe(II) and total Fe in ppb	Kukkadapu et al. (2004)	--
LSC	Sr90, Tc99, I129, in dpm/mL	*PNNL-AGG-RRL-002; Procedures vary slightly for different radioisotopes; McKinley et al. (2006) for Sr-90	--
Solid-State pH Electrode and Meter	pH, Bromide	AGG-PH-001	pH Measurement
X-ray Diffraction (XRD)	Mineralogy	RPL-XRD-PIP	Operation of Scintag Pad-V X-Ray Diffractor (RGD #62)
Scanning Electron Microscopy/ Energy-Dispersive X-ray Spectrometry (SEM/EDS)	Particle morphology, size, and qualitative elemental analysis	PNL-SP-3	Scanning Electron Microscopy/Energy Dispersive Spectrometry
Particle Size Distribution	--	PNL-MA-567, SA-3	Particle-size analysis (Pipette or hydrometer method); Wet sieve analysis will be used to remove sand-size particle

Method	Analysis	Document Number	Procedure Title
Hydraulic Conductivity	--	PNL-MA-567, SA-5	Falling head hydraulic conductivity
Water Retention	--	UFA-SK-01	Determination of water retention as a function of water content using open-flow centrifugation techniques
Water Content	--	PNL-MA-567, SA-7	Water Content
Bulk Density	--	PNL-MA-567, SA-8	Clod density/bulk density
Particle Density	--	PNL-MA-567, SA-9	Determining particle density; necessary for constant head hydraulic conductivity
Column Packing	--	WHC-IP-0635, GEL-3 Rev. 3	Moisture relationships of soils; necessary for constant head hydraulic conductivity
pH/EC	--	PNL-G-5-pH/EC	Measuring pH/EC of low-level radioactive solutions
Saturated column experiments	--	AGG-SAT-COL-001	Conducting saturated column experiments
Batch experiments	--	AGG-BSE-001	Batch sorption experiments
Surface Area	--	AGG-SA-001	Measuring Surface area
TIC/TOC	Inorganic C, organic C, total C	*PNNL-AGG-TOC-001	--
X-ray Fluorescence	Total analyses of sediments including Al, Si, K, Ca, Mg, Sr, Ti, Fe, Mn, Cu, Ni, Cr, Cs, U, and others.	*PNNL-AGG-OP-RGD74-001	--
Conventional Powder X-ray Diffraction	Mineral identity (% distribution)	Qafoku et al. (2005)	--
Digital Autoradiography	Identify locations of radioactivity in sediment thin section and mixtures of sand and silt-sized particles.	Zeissler et al. (2001); McKinley et al. (2001)	--
Scanning Electron Microscopy with WDS	High resolution imaging of particle morphology and atomic mass generally in sediment thin section; semi quantitative imaging of chemical distribution.	McKinley et al. (2005)	--

Method	Analysis	Document Number	Procedure Title
Transmission Electron Microscopy with Selected Area Diffraction (SAED)	Very high resolution of single mineral grains in cross section; local morphology, structure and atomic arrangement.	Zachara et al. (2006). Selected area diffraction patterns are interpreted using the JADE software (see below) using x-ray powder diffraction data (PDF) retrieved from a standards library (ICDD, 2003)	--
Electron microprobe	Quantitative, intermediate sensitivity chemical mapping in thin sections. Chemical transects across grain/particle boundaries.	Wang et al. (2005b), Catalano et al. (2006)	--
X-ray fluorescence microprobe	High sensitivity, semi quantitative mapping of element distributions in sediment thin sections at scales of 10 μ m.	Liu et al. (2004), Fredrickson et al. (2004)	--
X-ray absorption spectroscopy	Determination of element coordination structure, nearest neighbors, and bond distances in contaminated sediment.	Catalano et al. (2004), Catalano et al. (2006) Basic experimental synchrotron measurements are modeled with FEFF, FEFFIT, and IFEFFIT (see below) to extract molecular information.	--
Synchrotron diffraction	Identification of mineral structures in sediment thin sections.	Catalano et al. (2004). Mineral structures are derived by application of the FIT2D software (see below).	--
Cryogenic laser induced fluorescence spectroscopy (CLIFS)	Vibronic spectra of U(VI) in water and solids to establish molecular and mineralogic environment.	Wang et al. (2004) (for aqueous solutions); Wang et al. (2005a) (for solids). Data analysis is performed using the IGOR and Globals programs (see below).	--

Method	Analysis	Document Number	Procedure Title
Batch kinetic desorption experiments	Sediments are bathed in electrolyte of known composition and the time-variant release of contaminants and other solid associated ions are monitored by aqueous phase analyses.	Procedures vary as per element and its concentration. Examples include Liu et al. (2003) (Cs137); Liu et al. (2004) (U); McKinley et al. (2005) (Sr-90). Kinetic rate laws and rate constants are calculated from the data using microscopic, diffusion based transport models (see below). Steady state values can be used to establish thermodynamic parameters, such as the solubility product of a precipitated contaminant phase (e.g., Ilton et al. 2006).	--
Batch adsorption experiments	Sediments are bathed in electrolyte of known composition that has been spiked with a contaminant of interest. The adsorption of the contaminant is monitored as a function of pH, ionic strength, or ion composition.	Example procedures are equilibrium - Turner et al. (1996) (U) and Zachara et al. (2002) (Cs); kinetic - Liu et al. (2003) (Cs), Liu et al. (2004) (U), and McKinley et al. (2006) (Sr). Experimental results are fitted with various geochemical models (MINTEQA2; Geochemists Workbench; GMIN; or FITEQL see below) to identify suites of adsorption reactions (ion exchange or surface complexation).	--

Method	Analysis	Document Number	Procedure Title
Column experiments	Sediment (<2 mm or < 4 mm) is packed into a cylindrical plastic, glass, or stainless steel column. Electrolyte with or without a contaminant tracer is applied to the column to study the release (from contaminated sediment) or sorption/retardation (for uncontaminated sediments) of key contaminants of concern.	Qafoku et al. (2005). The basic experimental data that is in the form of chemical concentration as a function of leaching volume of fluid, must be modeled with various commercial and research codes to yield useable information. CXTFIT is used to fit physical transport parameters such as the dispersivity, while other models are linked with a solver of the advective-dispersion equation to describe 1-dimensional reactive transport. The reactive transport models include a commercial one (the Geochemists Workbench) and others assembled by the research team including the Distributed Rate Model (DRM) and the Dual Continuum Model (DCM). These are described below.	--
MINTEQA2 Version 4	Commercial software used to calculate aqueous speciation, precipitation/dissolution, and adsorption/desorption equilibria for low to intermediate-strength solutions.	Code published by Allison et al. (1991) and (1998) linked to a thermodynamic data base of our own synthesis (see below).	--
Geochemists Workbench	Commercial software to calculate geochemical equilibria, reaction network modeling, and reactive transport.	Geochemists Workbench Release 6. from Craig Bethke, Hydrogeology Program, University of Illinois.	--
CXTFIT	Commercial software for fitting column effluent data.	Toride et al. (1999).	--

Method	Analysis	Document Number	Procedure Title
FITEQL (V 4.0)	Commercial software used to calculate equilibrium constants and their statistics for aqueous, surface and precipitated phases from batch experimental data.	Herbelin and Westall (1999)	--
GMIN	An equilibrium geochemical model used to calculate aqueous speciation, precipitation/dissolution, and adsorption desorption equilibria for high ionic strength solutions. Maintained by PNNL.	Felmy (1995)	--
Spectral Fitting Software	Commercial software used to fit fluorescence emission spectra on U(VI) derived from CLIFS analyses. The fitting allows determination of the precise spectral wavelengths and deconvolutes spectral signatures resulting from multiple fundamental species.	Beechem et al. (1991)	--
Phase Identification for Powder Diffraction (JADE+, V 5)	Commercial software used to manipulate powder diffraction files are for comparison with reference spectra in for mineral identification.	Materials Data Inc., Livermore, CA; ICDD (2003)	--

Method	Analysis	Document Number	Procedure Title
Reactive Transport Modeling	The Dual Continuum Model (DCM) is used to model the reactive transport of contaminants 1-dimensional laboratory columns and in multidimensional field simulations. The model is a reaction-based simulator and requires significant parameterization using batch and column data, and physical measurements of sediment characteristics. Maintained by LANL.	Lichtner et al. (2000), Lichtner et al. (2001)	--
Empirical Kinetic Modeling	The distributed rate model (DRM) is used to empirically describe complex kinetic desorption/dissolution phenomena in sediment that is controlled by chemical kinetics or diffuse mass transport. The basic model describes kinetic phenomena using a statistical distribution of first order rate constants. Maintained at PNNL.	Culver et al. (1997)	--
Surface Complexation Model	The surface complexation model (SCM) is used to describe the surface chemical reactions of U(VI) that are responsible for its adsorption to vadose zone and aquifer sediments. Maintained by USGS.	Davis et al. (2004)	--

Method	Analysis	Document Number	Procedure Title
Thermodynamic Data Base	A large thermodynamic data base is maintained and constantly updated based on literature advances. The data base describes stability constants for aqueous complexes and solubility products for precipitated phases relevant to S&T research and issues. This data base is used in almost every S&T geochemical study. There are many hundreds of entries in the data base for a variety of contaminants that is used in MINTEQA@; Geochemists Workbench, and all of the reactive transport codes. Maintained at PNNL.	The data base relies on the following and many other sources: Grenthe et al. (1992) (U), Guillaumont et al. (2003) (U), and Rard (1999) (Tc)	--
<p>*The document number states ICP-AES, but the instrument in use is an ICP-OES. ICP-AES and ICP-OES are equivalent and refer to the same analytical technique.</p> <p>PNNL-AGG referenced procedures are from PNNL's Applied Geochemistry Group.</p>			

B.1 References

Allison JD, DS Brown, and KJ Novo-Gradac. 1991. *MINTEQA2/PRODEFA2, A Geochemical Assessment Model for Environmental Systems: Version 3.0 User's Manual*. U.S. Environmental Protection Agency, Washington, D.C.

Allison JD, DS Brown, and KJ Novo-Gradac. 1998. *MINTEQA2/PRODEFA2, A Geochemical Assessment Model for Environmental Systems: User Manual Supplement for Version 4.0*. U.S. Environmental Protection Agency, Washington, D.C.

Beechem JM, E Gratton, and WW Mantulin. 1991. *Globals Unlimited*. UIUC Publication.

Catalano JG, JP McKinley, JM Zachara, SC Smith, and GE Brown, Jr. 2006. "Changes in Uranium Speciation Through a Depth Sequence of Contaminated Hanford Sediments." *Environmental Science & Technology* (Submitted).

Catalano JG, SM Heald, JM Zachara, and GE Brown, Jr. 2004. "Spectroscopic and Diffraction Study of Uranium Speciation in Contaminated Vadose Zone Sediments from the Hanford Site, Washington State." *Environ. Sci. Technol.* 38:2822-2828.

Culver TB, SP Hallisey, D Sahoo, JJ Deitsch, and JA Smith. 1997. "Modeling the Desorption of Organic Contaminants from Long-Term Contaminated Soil Using Distributed Mass Transfer Rates." *Environ. Sci. Technol.* 31:1581-1588.

Davis JA, DE Meece, M Kohler, and GP Curtis. 2004. "Approaches to Surface Complexation Modeling of Uranium(VI) Adsorption on Aquifer Sediments." *Geochim. Cosmochim. Acta* 68:3621-3641.

Felmy AR. 1995. "GMIN. A Computerized Chemical Equilibrium Program Using a Constrained Minimization of the Gibbs Free Energy: Summary Report." In *Chemical Equilibrium and Reaction Models* (eds. RH Loeppert, AP Schwab, and S Goldberg) pp. 377-407, Soil Science Society of America.

Fredrickson JK, JM Zachara, DW Kennedy, RK Kukkadapu, JP McKinley, SM Heald, C Liu, and AE Plymale. 2004. "Reduction of TcO_4^- by Sediment-Associated Biogenic Fe(II)." *Geochim. Cosmochim. Acta* 68(15):3171-3187.

Grenthe I, J Fuger, RJM Konings, RJ Lemire, AB Muller, C Nguyen-Trung, and H Wanner. 1992. *Chemical Thermodynamics of Uranium*. North-Holland, Amsterdam.

Guillaumont R, T Fanghanet, V Neck, J Fuger, DA Palmer, I Grenthe, and MH Rand. 2003. *Update on the Chemical Thermodynamics of Uranium, Neptunium, Plutonium, Americium, and Technetium*. Elsevier.

Hammersley AP. 1997. *FIT2D: An Introduction and Overview*. Internal Report ESRF97HA02T; European Synchrotron Radiation Facility, Grenoble, France.

Herbelin A and J Westall. 1999. *FITEQL: A Computer Program for Determination of Chemical Equilibrium Constants from Experimental Data, Version 4.0*. Report 99-01. Oregon State University, Corvallis, Oregon.

ICDD. 2003. *JCPDS Powder Diffraction Files, PDF*. International Centre for Diffraction Data (ICDD), Newtown, Square, Pennsylvania.

Ilton ES, C Liu, W Yantasee, Z Wang, D Moore, and JM Zachara. 2005. "The Effect of Carbonate on the Dissolution of Synthetic Na-Boltwoodite." *Geochimica et Cosmochimica Acta* (Submitted).

Kukkadapu RK, JM Zachara, JK Fredrickson, and DW Kennedy. 2004. "Biotransformation of Two-Line Silica-Ferrihydrite by a Dissimilatory Fe(III)-Reducing Bacterium: Formation of Carbonate Green Rust in the Presence of Phosphate." *Geochim. Cosmochim. Acta* 68(13):2799-2814.

Lichtner PC. 2001. *FLOTTRAN: User's Manual*. Report No. LA-UR-02-2349, Los Alamos National Laboratory, Los Alamos, New Mexico.

Lichtner PC. 2000. "Critique of Dual Continuum Formulations of Multicomponent Reactive Transport in Fractured Porous Media, Dynamics of Fluids in Fractured Rock." *Geophys. Monograph* 122:281-298.

- Liu C, JM Zachara, W Yantasee, PD Majors, and JP McKinley. 2006. "Microscopic Reactive Diffusion of Uranium in the Contaminated Sediments at Hanford, USA: Characterization and Modeling." *Water Resources Research* (Submitted).
- Liu C, JM Zachara, O Qafoku, JP McKinley, SM Heald, and Z Wang. 2004. "Dissolution of Uranyl Microprecipitates in Subsurface Sediments at Hanford Site, USA." *Geochim. Cosmochim. Acta* 68(22):4519-4537.
- Liu C, JM Zachara, SC Smith, JP McKinley, and CC Ainsworth. 2003. "Desorption Kinetics of Radiocesium from Subsurface Sediments at Hanford Site, USA." *Geochim. Cosmochim. Acta* 67(16):2893-2912.
- McKinley JP, JM Zachara, SC Smith, and C Liu. 2006. "Cation Exchange Reactions Controlling Desorption of $^{90}\text{Sr}^{2+}$ from Coarse-Grained Contaminated Sediments from the Hanford Formation, Washington." *Geochimica et Cosmochimica Acta* (Submitted).
- McKinley JP, JM Zachara, C Liu, and SC Heald. 2005. "Precipitation of Waste Uranium as a Uranyl Silicate in Microfractures." *Geochimica et Cosmochimica Acta* (In press).
- McKinley JP, RJ Serne, JM Zachara, CJ Zeissler, and RM Lindstrom. 2001. "The Distribution and Retention of ^{137}Cs in Sediments at the Hanford Site, Washington." *Environ. Sci. Technol.* 35:3433-3441.
- Newville M. 2001a. "IFEFFIT: Interactive XAFS Analysis and FEFF Fitting." *J. Synch. Rad.* 8:322-324.
- Newville M. 2001b. "EXAFS Analysis Using FEFF and FEFFIT." *J. Synch. Rad.* 8:96-100.
- Qafoku NP, JM Zachara, C Liu, PL Gassman, OS Qafoku, and SC Smith. 2005. "Kinetic Desorption and Sorption of U(VI) During Reactive Transport in a Contaminated Hanford Sediment." *Environ. Sci. Technol.* 39:3157-3165.
- Rard JA, MH Rand, G Anderegg, and H Wanner. 1991. *Chemical Thermodynamics of Technetium*, Chapter 3; (MCA Sandino and E Osthols, eds.), Elsevier, The Netherlands, Amsterdam, pp. 544.
- Toride N, FJ Leij, and MT van Genuchten. 1999. *The CXTFIT Code for Estimating Transport Parameters from Laboratory or Field Tracer Experiments*. U.S. Salinity Laboratory.
- Turner GD, JM Zachara, JP McKinley, and SC Smith. 1996. "Surface-Charge Properties and UO_2^{2+} Adsorption of a Subsurface Smectite." *Geochim. Cosmochim. Acta* 60:3399-3414.
- Wang Z, JM Zachara, PL Gassman, O Qafoku, and J Catalano. 2005a. "Fluorescence Spectroscopy of U(VI)-Silicates and U(VI)-Contaminated Hanford Sediment." *Geochim. Cosmochim. Acta* 69(6):1391-1403.
- Wang Z, JM Zachara, JP McKinley, SC Smith, and SM Heald. 2005b. "Cryogenic Laser Induced U(VI) Fluorescence Studies of a U(VI) Substituted Natural Calcite: Implications to U(VI) Speciation in Contaminated Hanford Sediments." *Environ. Sci. Technol.* 39:2651-2659.

Wang Z, JM Zachara, W Yantasee, PL Gassman, C Liu, and AG Joly. 2004. "Cryogenic Laser Induced Fluorescence Characterization of U(VI) in Hanford Vadose Zone Pore Waters." *Environ. Sci. Technol.* 38(21):5591-5597.

Webb SM. 2005. "SIXPack: A Graphical User Interface for XAS Analysis Using IFEFFIT." *Phys. Scr.* T115, 1011-1014.

Zachara JM, SC Smith, C Liu, JP McKinley, RJ Serne, and PL Gassman. 2002. "Sorption of Cs⁺ to Micaceous Subsurface Sediments from the Hanford Site, USA." *Geochim. Cosmochim. Acta* 66:193-211.

Zeissler CJ, RM Lindstrom, and JP McKinley. 2001. "Radioactive Particle Analysis by Digital Autoradiography." *J. Radioanal. Nuclear Chem.* 248(2):407-412.

Distribution

No. of Copies

16 Internal Distribution

Pacific Northwest National Laboratory
P.O. Box 999
Richland, WA 99352

(Note that distribution of the document will be through placement on the PNNL SharePoint Site and notification to the individuals below)

C. F. Brown	P7-22
R. W. Bryce	K6-75
L. R. Burns	K6-94
C. A. Carlson	K9-78
N. J. Fix	J2-56
M. D. Freshley	K9-33
J. S. Fruchter	K6-96
C. T. Kincaid	K9-33
G. V. Last	K6-81
J. H. Maday	J2-56
C. J. Murray	K6-81
R. E. Peterson	K6-75
R. J. Serne	P7-22
R. M. Smith	K6-96
M. D. Sweeney	K6-75
A. L. Ward	K9-33